

To: Bjorn	Fax: 512-244-0853		
From: Bill Baber & Adam Mora	n Date: 5/10/12		
Re: U Pick It	Pages: 87		
☐ Urgent ☐ For Review ☐	☐ Please Reply		

Contact: Bill Baber 402-957-6498 or Adam Moran 913-207-7879



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 7 901 NORTH 5TH STREET KANSAS CITY, KANSAS 66101

MAR 2 1 2012

Mr. Adam Moran General Manager U-Pick-It 7700 East Winner Road Kansas City, Missouri 66103

RE:

U-Pick-It

Kansas City, Missouri

EPA RCRA ID No.: Non-notifier

Dear Mr. Moran:

On February 9-10, 2012, a representative of the U.S. Environmental Protection Agency (EPA) inspected your facility. The inspection was conducted under the authority of Section 3007 of the Resource Conservation and Recovery Act (RCRA). A copy of the inspection report is enclosed for your information.

The EPA is presently reviewing the findings of the report to determine your facility's compliance with the applicable statutes, permits, or regulations. If it is determined that violations exist, the EPA reserves all rights it may have to take appropriate enforcement action, regardless if any violations were subsequently corrected.

If there are any questions regarding this report or actions that you may want to take, please contact me at (913) 551-7164.

Sincerely,

Deborah Bredehoft Compliance Officer

Waste Enforcement and Materials Management Branch

Enclosure

ce: Mr. Dennis Hansen, Missouri Department of Natural Resources

Missouri Department of Natural Resources Kansas City Regional Office



REPORT OF RCRA COMPLIANCE EVALUATION INSPECTION

AT

U-PICK-IT

7700 E. Winner Road Kansas City, MO 66103 (816) 241-7548

EPA ID Number: Non-notifier

ON

February 9-10, 2012

BY

U.S. ENVIRONMENTAL PROTECTION AGENCY
Region VII
Environmental Services Division

1.0 INTRODUCTION

At the request of the Air and Waste Management Division (AWMD), I performed a Resource Conservation and Recovery Act (RCRA) compliance evaluation inspection at U-Pick-It (UPI) located in Kansas City, MO on 2/9-10/2012. I conducted the inspection under the authority of RCRA Section 3007(a), as amended. During the inspection, I collected the information and data necessary to determine compliance with the applicable regulatory and statutory requirements. This report and attachments present the results of the inspection. I conducted the inspection as a Level B Multi-Media Inspection and the Multi-Media Screening Checklist is included as attachment 1. Based on the information obtained during the course of the inspection, I inspected the facility as a non-generator of known hazardous waste, used oil generator, used oil collection center, and small quantity handler of universal waste. However, additional hazardous waste determinations need to be made that may affect the non-generator status determination. According to the EPA RCRAInfo database, this facility has not been previously inspected.

2.0 PARTICIPANTS

U-Pick-It, Kansas City, MO (UPI-KCMO):

Adam Moran, General Manager (about three years in position and five years with the company)

Nick Tordoff, Assistant General Manager (about four years in position and nine years with the company)

(See attachment 2 for copy of business cards.)

U.S. Environmental Protection Agency (EPA): Dedriel L. Newsome, Environmental Engineer

3.0 INSPECTION PROCEDURES

On 2/9/2012 at about 9:00A.M., I arrived at UPI-KCMO and met Mr. Moran. I explained the purpose and procedures of the inspection and presented him with my EPA credentials. He was made aware of the facility's confidentiality rights and informed that a Confidentiality Notice would be provided at the end of the inspection to make any claims. He was provided with a copy of Section 3007 of RCRA and U.S. Federal Code 1001 and 1002, concerning false statements and documents, to read.

I discussed with Mr. Moran the facility operations, wastes generated and waste management practices. I conducted a visual inspection of UPI-KCMO accompanied by Mr. Moran and Mr. Tordoff. I reviewed various records including facility layouts and shipping documents. Information collected during the inspection is documented on the Entry/Exit Checklist and the Missouri Department of Natural Resources (MDNR) Used Oil Generator, Used Oil Collection Center, and Universal Waste Small Quantity Handler inspection checklists (see attachments 3A through 3D). I completed documents and collected photocopies that are included as attachments 1 through 14. Also, I collected photographs with a digital camera. They are included as photos 1 through 51 and are listed in the attached photo log.

At the conclusion of the inspection, I summarized the findings and recommendations with Mr. Moran. I provided Mr. Moran with a Confidentiality Notice, a Receipt for Documents and a Notice of Violation (NOV) which he signed as acknowledgment of receipt (see attachments 4 through 6). The compliance assistance documents provided during the inspection are listed on the Entry/Exit Checklist included as attachment 3A, page 2. I informed Mr. Moran of the MDNR hazardous waste website that contains hazardous waste technical guidance documents and other helpful RCRA information.

4.0 Findings and Observations

4.1. General Information

There are two UPI vehicle salvage yards located in the Kansas City area. They consist of this UPI-KCMO facility and another located at 1142 S. 12th St, Kansas City, KS (UPI-KCK). The UPI-KCK facility was started first around 2004, and then the UPI-KCMO facility was started around 2005. UPI also has a local corporate office located at 117 W. 20th St., Kansas City, MO. Mr. Moran stated that the local corporate office is only an office where both salvage yards send their paper work for handling.

UPI is associated with U-Pull-It, although Mr. Moran did not know exactly how legally. He stated that both are owned by Harry Henson and that U-Pull-It handles UPI's accounts payable. U-Pull-It has a corporate office located at 5705 S. 60th St., Suite 105 in Omaha, NE. Mr. Moran was not sure how long U-Pull-It has been in business, but stated that it has been a long time. There are several other related salvage yard companies owned by Mr. Henson located across the country. They include two in Omaha, NE, one in Lincoln, NE, and one in Prescott, AZ. Attachments 7A and 7B includes some company information obtained from both companies' websites located at www.upickitkc.com and www.upullitomaha.com.

The UPI-CMO site is about 13 acres which Mr. Hansen also owns (i.e., they do not lease the property). The site has one large building that contains a first floor and partial second floor (see attachments 8A and 8B for facility layouts and aerial photos). Mr. Moran stated that they do not have or use any facilities/buildings other than those mentioned above.

UPI-KCMO has about 20 full-time employees. During the summer, the facility is operated from 8:00A.M. to 7:00P.M., seven days a week. During the winter, it is operated from 8:00AM to dark, seven days a week. Vehicle processing takes place on only Monday through Friday. Mr. Moran stated that UPI-KCMO does not have an environmental person on-site. He stated that U-Pull-It has one environmental manager, Bill Baber, located at the U-Pull-It corporate office in Omaha, NE. Mr. Moran stated that Mr. Baber assists UPI-KCMO with compliance, visits the site about two to four times per month, and talks with him about two times a week.

4.2. Facility Operations

UPI-KCMO is a vehicle (autos and trucks) salvage yard. Mr. Moran stated that UPI-KCMO processes about 150 vehicles and one diesel vehicle per month. He stated that they process all vehicle types of various ages. He stated that the oldest he has seen is 1955 and the latest is 2011. Mr. Moran explained the vehicle process as follows (see attachment 8A for locations referenced on facility layout):

- 1. Buy scrap vehicles with legitimate titles from various individuals, tow companies, dealers, etc. The vehicle's information is entered into a computer program to determine the price UPI-KCMO is willing to pay for them.
- 2. Pick-up, or the seller drops off, the scrap vehicles.
- 3. Dispatch weighs the vehicles, assigns bar codes, and enters the vehicles' specifications (specs) into a computer database. The database tracks the make, model, year, date received, who purchased from, date processed, etc.
- 4. Place the vehicles in the Holding Area.
- 5. Move the vehicles to the Rack Area where fluids are removed. The fluids are removed by placing the vehicles on an overhead rack (see photos 40 and 46) and draining them. The fluids removed are the diesel (punch hole to drain), anti-freeze (cut bottom hose to drain or use a wand pump), oil (remove plug to drain), transmission fluid (punch hole in bottom of oil pan to drain) and gasoline (punch hole to drain).
- 6. Move the vehicles to the Pop Hood Area where additional fluids are pumped out including power steering, brake, and windshield wiper. Also, tire lug nuts are loosened, and trash, batteries and mercury switches are removed. Mr. Moran stated that UPI-KCMO does not remove fuel filters, used oil filters, headlights, brake pad/shoes and air bags.
- 7. Store the vehicles in their designated yard area (GM, Ford, Chrysler and Imports).
- 8. Customers shop throughout the yard areas, remove desired vehicle parts, and take them to the Sales Office for purchase.
- 9. Pull and replace the vehicles in the yard areas daily, Monday through Friday. Mr. Moran stated that on average, about 30 vehicles are pulled and replaced per day. He stated that they pull the oldest first, and on average the vehicles remain in the yard areas about 60 to 90 days.

- 10. Take the pulled vehicles to the Break Down Area where all remaining valuable parts/pieces are removed. This includes non-ferrous parts/pieces such as aluminum wheels, drums, copper, etc.
- 11. Move the vehicles to the Crusher Area where engines and transmissions are removed, copper wires are removed from the motors, and the vehicles are crushed flat in a crusher.
- 12. Load crushed vehicles onto semi-trailers and transport them to a shredder for metal recycling.

UPI-KCMO also has a Core Return Area where customers receive credit for parts including, aluminum and steel rims, tires, etc.

General maintenance (including oil changes) on company vehicles is conducted on-site. This maintenance is done in the Rack Area usually on Saturdays when no vehicle processing is occurring. All significant vehicle maintenance is conducted off-site at UPI-KCK by the same mechanic that conducts the general maintenance at UPI-KCMO.

4.3. RCRA Status

At the time of the inspection, I determined that UPI-KCMO was a non-generator of known hazardous waste, used oil generator, used oil collection center, and a small quantity handler of universal waste. However, additional hazardous waste determinations need to be made, as discussed below, that may affect the non-generator status determination. The checklists completed during the inspection are included as attachments 3A through 3D. According to the EPA RCRAInfo database, UPI-KCMO had not notified as a hazardous waste generator. I provided Mr. Moran an EPA RCRAInfo Handler Information Report which was completed (see attachment 9).

It should be noted that UPI-KCMO is located on property previously owned by AK Steel, Kansas City, MO. AK Steel had a RCRA permit and solid waste management units (SWMU) were identified on the UPI-KCMO's site. AK Steel is currently going through corrective action.

4.3. Wastes Streams

The following table lists the waste streams discussed.

	05-10-'12 11:25 FROM-U- PICK IT 816-457-6064
OFF-SITE MANAGEMENT	The used oil is pumped from the storage tank by Heritage-Crystal Clean, Kansas City, KS (see attachment 10 for latest shipping document). Mr. Moran was not sure how Heritage-Crystal Clean handled the used oil. About a year ago, the used oil was collected by RS Used Oil, Kansas City, KS.
ON-SITE MANAGEMENT	The used oil is handled as follows: 1. Scrag Vehicles — There is a sump in the Rack Area located under the two overhead racks where the used oil is pumped from the surae oil is pumped from the surae from the scrap vehicles. The used oil is pumped from the surae from the scrap vehicles and photos 9 and 11). I observed about an inch of used oil is collected for shipment. The other vehicle fluids are sump. 1. On-site Maintenance is collected in a container or pumped from the scrap vehicles into a container. The container is emptied into the above sump. 2. On-site Maintenance is collected in a containers of used oil on-site. The containers bring containers of used oil on-site. The containers are emptied into a 275-gallon tote located in the Core Return Area (see photo 45). The used oil in the tote is emptied into the above sump.
ESTIMATED GENERATION RATE	The used oil is generated as follows: 1. Scrap Vehicles – The scrap vehicle used oil is generated on average about 300 gallons per week according to Mr. Moran. The amount last shipped was 500 gallons on 2/3/2012 (see attachment 10). On 2/9/2012 during the inspection, a load was being collected for shipment. 2. On-site Maintenance— The general maintenance used oil is included in the above scrap vehicles' used oil generation rate. 3. Customers – Mr. Moran estimated that approximately one 275-gallon tote is filled per year.
HAZARDOUS WASTE DETERMINATION	as used oil.
GENERATION PROCESS	28 - 4 W
WASTENAME	[See 40]
1 444	

OFF-SITE MANAGEMENT		ing containers of used satomers, but the the parking lot. coming a problem in il containers into the pring their used oil onustomers to work on I also, informed Mr.	and he stated that IIDI.
ON-SITE MANAGEMENT	National Information — Mr. Moran believed that the used oil is fuel blended, but was not sure how Heritage-Crystal Clean handled their used oil. I asked for this information to verify that the used oil was not being sent directly to a burner, and therefore making UPI-KCMO a used oil marketer (see attachment 5). Izaardous Waste Determination (NOV #3A) - According to 10 CSR 25-2.62(1) -40 CFR 262.11, a hazardous waste determination is to be made on all solid waste. In the northeast side of the Pop Hood Area, I observed five drums being stored (see attachment 8A for layout and photos 13 through 17). Mr. Moran estimated five drums being stored (see attachment 8A for layout and photos 13 through 17). Mr. Moran initially believed that the drums contained some diesel fuel that was contaminated in some unknown way. However, he stated hat after checking with other employees, the five drums contained waste cleaned out of the Rack Area sump about six to eight months ago. He stated that they needed to a hazardous waste determination on this waste and decide how to dispose of it. It should be noted that I observed a spill around these five drums as shown in photo 16. Jeal Oil Collection Center (NOV #2) - According to 10 CSR 25-11.279(2)(1)2, used oil collection centers must notify the denartment of its used oil collection Center.	ctivities. Mr. Moran stated that UPI-KCMO had not registered or received any license as a used oil collection center. He stated that customers bring containers of used il on-site and adds it into a tote located in the Core Return Area (see photo 45). He stated that UPI-KCMO does not solicit the used oil from the customers, but the ustomer just brings it on-site and leaves it. Mr. Moran stated that prior to six months ago, the customers were leaving the containers of used oil in the parking lot. herefore, his employees would have to collect these containers from the parking lot. Mr. Moran stated that therefore, to keep the used oil from becoming a problem in the parking lot, and because they cannot always catch the customer and make them remove the used oil, they told the customers to dump the used oil containers into the located in the Core Return Area. Mr. Moran did not think UPI-KCMO was a collection center because they were not asking any customers to bring their used oil on-site. I asked Mr. Moran if the customers generated the used oil on-site while working on their personal vehicles. He stated that they do not allow customers to work on reir vehicles on-site. Since it appears that UPI-KCMO was collecting household do-it-yourselfers used oil, I inspected them as a collection center. I also, informed Mr.	foran that I would verify with the state if UPI-KCMO was a collection center that needed to notify. I contacted Tom Judge, MDNR, on 2/15/2012 and he stated that UPI-ICMO would be concidered a collection center and needed to notify the denotions.
ESTIMATED GENERATION RATE	therefore making UPI-KCN therefore making UPI-KCN (1)—40 CFR 262.11, a haza see attachment 8A for layou uld equal about four full 55-quined some diesel fuel that vout of the Rack Area sump. It should be noted that I obtained oil collection center.	icense as a used oil collectic He stated that UPI-KCMO on this ago, the customers were lot. Mr. Moran stated that the remove the used oil, they collection center because the king on their personal vehicle do-it-yourselfers used oil, I	at needed to notify. I contact ant.
MAZAKOOUS WASTE DETERMINATION	sed oil is fuel blended, I directly to a burner, and mg to 10 CSR 25-5.262 we drums being stored (d two partially full) wo wed that the drums contionatined waste cleaned ide how to dispose of it.	istered or received any large (see photo 45). ated that prior to six mc ainers from the parking customer and make their hink UPI-KCMO was a se oil on-site while worl as collecting household	as a collection center the
GENERATION PROCESS	Nuclinonal Information — Mr. Moran believed that the used oil is fuel blend information to verify that the used oil was not being sent directly to a burner, fazardous Waste Determination (NOV #3A) - According to 10 CSR 25-5. In the northeast side of the Pop Hood Area, I observed five drums being storatal volume between all five (three approximately full and two partially full) hown in photos 13 through 17. Mr. Moran initially believed that the drums hat after checking with other employees, the five drums contained waste cleave a hazardous waste determination on this waste and decide how to dispose Ised Oil Collection Center (NOV #2) — According to 10 CSR 25-11.279(2)	it into stated that UPI-KCMO had not regit in the state and leaves it. Mr. Moran styces would have to collect these contoccause they cannot always catch the re Return Area. Mr. Moran did not tran if the customers generated the use. Since it appears that UPI-KCMO w	foran that I would verify with the state if UPI-KCMO was a collection center that n CMO would be considered a collection center and needed to notify the department.
# WASTENAME	Auditional Informal information to verify lazardous Waste D on the northeast side of a volume between hown in photos 13 th hat after checking with a fazardous waste Ised Oil Collection	ctivities. Mr. Moran il on-site and adds it ustomer just brings i herefore, his employ te parking lot, and bote located in the Corite. I asked Mr. Morite. I asked Mr. Moriter vehicles on-site.	foran that I would ve CMO would be con

P0008/0088 F-795

attachment IIB for shipping documents).

azardous Waste Deter ade on all solid waste. odel vehicles, after 199 PI-KCMO processes m garding the amount of					
	azardous Waste Defermination Verification / Additional Information - According to 10 CSR 25-5.262(1)-+40 CFR 262.11, a hazardous waste defermination is a decount of the Anti-freeze sheet included in the MDNR Preventing Pollution During Vehicle Salvage guide, used anti freeze from the later of the solid waste. According to the Anti-freeze sheet included in the MDNR Preventing Pollution During Vehicle Salvage guide, used anti freeze from the later of the new solid should be attachment and the state of the state of the salvage and the salvage anti-freeze shipments shown in attachment 11B (see attachment 5).	trachment IIC). As sta cussed above in Section t three anti-freeze shipr	cording to 10 CSK 25-5.262 IR Preventing Pollution Durited above, UPI-KCMO recent 42, UPI-KCMO tracks the neuts shown in attachment	rmination Verification / Additional Information - According to 10 CSR 25-5.262(1)—40 CFR 262.11, a hazardous waste determination is to be According to the Anti-freeze sheet included in the MDNR Preventing Pollution During Vehicle Salvage guide, used anti freeze from the late 55, is not RCRA hazardous (see attachment 11C). As stated above, UPI-KCMO receives all types of vehicles. Mr. Moran stated that he believes nostly late model vehicles. As discussed above in Section 4.2, UPI-KCMO tracks the year of all vehicles processed. I asked for verification late vehicles processed for the last three anti-freeze shipments shown in attachment 11B (see attachment 5).	e determination is to be eeze from the late stated that he believes d for verification
Waste Gasoline	Waste gasoline is drained from the scrap vehicles.	The waste gasoline is used as is on-site as a fuel and is therefore, not a RCRA solid waste. However, see discussion below for waste accumulated in tank containment.	The waste gasoline generation rate varies significantly according to Mr. Moran, but he estimated on average about 500 gallons per week.	The waste gasoline is drained into a 55-gallon drum and at the time of generation is pumped into a 500-gallon above ground storage tank (see photos 9 and 11). It is dispensed on-site into company vehicles for use. Also, see discussion below for waste accumulated in tank containment.	The waste gasoline is not shipped off-site. However, see discussion below for waste accumulated in tank containment.
ditional Information, or what the steep the used oil if Filters and Wet, it states that tainment facilities containment with the contai	dditional Information Cleaning of Tank – Mr. Moran stated that the fuel tank was cleaned once in their five years of operation. However, he did not recall when, by hom, or what they did with any fuel/waste removed. I asked for this additional information (see attachment 5). **Aste Fuel in Tank Containment / Possible Hazardous Waste Determination – I observed about an inch of waste gasoline in the storage tank containment, along with neat gasoline filters (see photos 8 and 10 and waste stream #4). Mr. Moran stated that the waste gasoline will either be pumped out by Heritage-Crystal Clean when they silters the used oil, or it will be cleaned out when they have the fuel storage tank cleaned again. I provided Mr. Moran with the MDNR Managing Gasoline Dispenser well Filters and Wastes Associated with the Operation of Fuel Dispensing Systems fact sheet (see attachment 12). After the inspection and further review of the fact neet, it states that the Missouri Department of Agriculture 2 CSR 90-30 citation states that "Water or product shall not be allowed to accumulate within any secondary ontainment facility, this includes dikes and remote impoundments. Accumulated water and/or product within a secondary containment facility shall be removed and sposed of in a manner that is in compliance with applicable rules of the Department of Natural Resources." Based on this fact sheet information, how the waste fuel in econtainment will be disposed may be a solid waste, and therefore, a hazardous waste. It should be noted that according to 10 CSR 25-11.279(B) -+ 40 CFR 279.10(d), ixtures of used oil and fuels are subject to used oil regulations.	stated that the fuel tan isked for this additional waste Determination m #4). Mr. Moran statk ve the fuel storage tank Fuel Dispensing System adments. Accumulated therefore, a hazardour ations.	k was cleaned once in their f information (see attachmen at that the waste gasoline wi cleaned again. I provided has fact sheet (see attachmen states that "Water or produ d water and/or product with nent of Natural Resources." s waste. It should be noted to	ive years of operation. However, he di t 5). of waste gasoline in the storage tank c ill either be pumped out by Heritage-Ci fr. Moran with the MDNR Managing in 12). After the inspection and further it shall not be allowed to accumulate with a secondary containment facility shall hat according to 10 CSR 25-11.279(B) that	id not recall when, by ontainment, along with rystal Clean when they Gasoline Dispenser review of the fact within any secondary II be removed and how the waste fuel in) — 40 CFR 279.10(d).
Waste Gasoline Filters	Waste gasoline filters are generated from the fuel pipe line leading into the waste fuel storage tank (see waste stream #3 and photos 8 through 10). According to Mr. Moran, the fuel filters on the scrap vehicles are not removed. Therefore, they are crushed with the scrap vehicles that are sent for recycling (see waste stream #9).	Drained waste gasoline filters that are reclaimed as scrap metal are RCRA exempt. However, a determination had not been made on the undrained waste gasoline filters (see discussion below).	Mr. Moran estimated about one waste gasoline filter is generated every two weeks. I observed six speut filters inside the tank containment and two outside the containment stated were generated in the past one and half to two months (see photos 8 and 10).	The waste gasoline filters are collected with the general trash which is sent with the crushed vehicles to a metal recycler (see waste stream #16).	The waste gasoline filters are collected with the general trash which is sent with the crushed vehicles to a metal recycler (see waste stream #16).

# WASTE NAME GENERATION PROCESS DECTREMINATION GENERATION NATE CREATION NATE CONSTITEMANAGEMENT DECTREMINATION OF ACCORDING TO 10 CSR 25.5.202(1)—40 CFR 25.1.1, a hazardous waste determinations (NOV #3D). According to 10 CSR 25.5.202(1)—40 CFR 25.1.1, a hazardous waste determination is to be made on all solid waste. I have to made on and a high to we mentality seemed to container per include of waste first greater the following concurring waste metal gesolute by premise Their Files The MONS factors of the September of California and an earth for metal or solid services for container per their managed as some metal for waste factors and their to we made and the service of the factors and their to we container per their their services and mark to we have the service of a factor and service of the per their their services and mark to we have the service of the services	**************	05-10-'12 11:25 FROM-U-	- PICK IT	816-457-6064	T-422
HAZARDOUS ESTIMATED CONERATION PROCESS DETERMINATION RATE CONSISTE MANAGEMENT	OFF-SITE MANAGEMENT) We are an example .	The used oil filters are collected with the general trash which is sent with the crushed vehicles to a metal recycler (see waste stream #16).	The waste diesel is not shipped off-site.	The waste refrigerant is collected by Rapid Recovery, Phoenix, Arizona, for recycling (see attachment 13 for latest invoice).
# WASTE NAME GENERATION PROCESS DETRAINING NOT A MASTE DETRAINING SEND DETRAINING NOT ## A STE DETRAINING NOT ## A STE DETAINING HE BESTIMATED TO THE REAL THE MONTH STEP THE MONTH MAN STEP THE MONTH MAN STEP THE MONTH MAN STEP THE MONTH STEP THE MONTH MAN STEP THE MAN STEP THE MAN STEP THE MONTH MAN STEP THE MONT	ON-SITE MANAGEMENT	ardous waste determination is to be ma were generated in the past one and a ha hasoline Dispenser Fuel Filters and Wo penser filters: (1) they can be managed ed container prior to being sent for recy ing spent filters in a sump containmen teristically hazardous for benzene (see d them to be a solid waste for which a	The used oil filters are drained and collected with the general trash which is sent with the crushed vehicles to a metal recycler (see waste stream #16).	The waste gasoline is drained into a container and at the time of generation is pumped into a 500-gallon above ground storage tank (see photos 9 and 11). It is used on-site in company equipment (forklifts, skids loaders and front end loaders).	The waste refrigerant is collected in cylinders by UPI-KCMO.
HAZARDOUS WASTE NAME GENERATION PROCESS DETERMINATION	ESTIMATED GENERATION RATE	(1)—40 CFR 262.11, a hazanent that Mr. Moran stated il. The MDNR Managing C ng waste metal gasoline dislif, dried, and stored in a closiculture regulations; (4) storthey are likely to be charactere not drained, I determine	Mr. Moran estimated at most about five used oil filters are generated per month.	The waste diesel generation rate varies significantly according to Mr. Moran, but he estimated about 20 gallons per month.	The waste refrigerant generation rate varies according to Mr. Moran. It was last reclaimed on 10/12/2011 (see attachment 13 for the latest invoice).
Fazardous Waste Determinations (NOV #3D) - Accord bserved six spent filters inside the tank containment and hotos 8 and 10). The six inside the containment sat in ab the Operation of Fuel Dispensing Systems fact sheet states redrained of all liquids and are sent for metal recycling; ever be placed or drained in containment sumps as it violos) if they are not recycled, then they should be considered as spent filters I observed being stored for the past one an etermination had not been made. Used Oil Filters Used oil filters are generated from maintenance on the company vehicles are not renoved. Therefore, they are cushed with the scrap vehicles that are sent for recycling (see waste stream #9). Waste Diesel Waste diesel is drained from the scrap vehicles (about one diesel vehicle is processed per month). Waste Waste refrigerant is drained from the scrap vehicles.	HAZARDOUS WASTE DETERMINATION	fing to 10 CSR 25-5.262 two outside the contains out an inch of waste fue is the following concernit (2) they must be drained lates Department of Agr I hazardous waste since ad half to two months w	The used oil filters being reclaimed as a scrap metal are RCRA exempt.	The waste diesel is used as is on-site as a fuel and is therefore, not a RCRA solid waste.	The waste refrigerant being reclaimed is RCRA exempt.
# WASTE NAME [azardous Waste] bserved six spent filters 8 and 10). The Operation of Figure drained of all fiques blaced or down the spent filters I obsert spent spent filters I obsert spent filters I obsert spent spent filters I obsert spent filters I obsert spent spent filters I obsert spent	in the state of th	Determinations (NOV #3D) - Accordifiers inside the tank containment and he six inside the containment sat in about a Dispensing Systems fact sheet states uids and are sent for metal recycling; rained in containment sumps as it vio cycled, then they should be considered served being stored for the past one are of been made.	Used oil filters are generated from maintenance on the company vehicles and equipment. According to Mr. Moran, the used oil filters on the scrap vehicles are not removed. Therefore, they are crushed with the scrap vehicles that are sent for recycling (see waste stream #9).	Waste diesel is drained from the scrap vehicles (about one diesel vehicle is processed per month).	Waste refrigerant is drained from the scrap vehicles.
g yang pampa manan pagan pampa pang pang pang pang pang pang pang pa	1	lazardous Waste I. bserved six spent fi hotos 8 and 10). The Operation of Fue e drained of all liques be placed or drainer by if they are not recie spent filters I obsidermination had no		Waste Diesel	Waste Refrigerant

aspection and further review of the Rapid Recovery invoice, Rapid Recovery collected mixed refrigerants from two cylinders (see attachment 13). How Rapid Recovery fixed Refrigerants - According to 10 CSR 25-4.261→40 CFR 261.4(b)(12), used chlorofluorocarbon (CFC) refrigerants being reclaimed are exempt. After the andled the mixed refrigerant (i.e., was it reclaimed or disposed) was not discussed during the inspection.

P0010/0088 F-795

¥. 11 . 2	95-10-12 11:26 FROM-U-	• FICK IT 816-4	157-6064	T-422 P0011/
OFF-SITE MANAGEMENT	The waste batteries are collected by Exide Technologies for recycling (see attachment 14 for latest shipping document).	The scrap metal is taken daily by UPI-KCMO to various scrap metal shreddens for recycling. They include Midwest Metal Scrap located next door, Advantage Metal Recycling, Kansas City, MO and Alters Metal Recycling,	The spent 4ft lamps have not been shipped off-site and the other unknown spent lamps in the process areas have not been changed according to Mr. Moran. He stated that Redford Electric	takes the spent Dispatch Office spent lamps, but he is not sure what is done with them.
ON-SITE MANAGEMENT	The waste lead-acid batteries are either collected in the Sales Office to be sold or are accumulated on a pallet in the Pop Hood Area to be reclaimed.	The scrap metal is collected in containers.	The spent 4ft lamps are being accumulated in the Telephone System Room (see attachment 8A and photos 6 and 7). Mr. Moran stated that the other unknown spent lamps in the process areas have not been changed. He stated that Redford Electric removes and takes the Dispatch Office spent lamps.	
ESTIMATED GENERATION RATE	The waste lead-acid batteries generation rate varies according to Mr. Moran, which he estimated on average to be about 120 batteries per week. Three pallets of batteries were last shipped off-site around February 2012 (see	Mr. Moran stated that the scrap metal generation rate varies, but estimated they ship about 13 semi-tractor trailers (about 80,000 pounds gross weight each) per week.	Mr. Moran did not know the generation rate of all the spent lamps. However, he stated that he has accumulated the 11 spent 4ft lamps currently in storage during his three years at the facility (see photos 6 and 7). Mr. Moran stated that the	other unknown spent lamps in the process areas have not been changed, and that he did not know the generation rate for the Dispatch Office spent lamps.
HAZARDOUS WASTE DETERMINATION	The waste lead-acid core batteries are handled per 10 CSR 25-7.266 → 40 CFR Part 266, Subpart G.	The scrap metal is managed as scrap metal being recycled.	A hazardous waste determination had not been made on the spent lamps.	*
GENERATION PROCESS	Waste lead-acid batteries are removed from the scrap vehicles. Mr. Moran stated that they do not generate any other types of batteries.	Scrap metal is segregated into ferrous and non-ferrous. The ferrous scrap includes the crushed scrap vehicles. The non-ferrous scrap includes copper, aluminum (Al radiators) and catalytic converters. Motors and transmissions may be either ferrous or non-ferrous depending on type. This waste stream also includes any scrap vehicle crushed pieces (glass, plastic) that are periodically scooped off the floor and put in a crushed vehicle.	Spent lamps are generated when the building's spent lamps are changed. The types used on-site include 4th fluorescent lamps and other unknown types in the process areas. Mr. Moran stated that they have an electrician, Redford Electric, Kansas City, MO, that changes the spent lamps	(type unknown) located in the Dispatch Office. Lamps from scrap vehicles are not removed.
# WASTE NAME	Waste Lead-Acid Batteries	Scrap Metal	Spent Lamps	

		•				
WAS	# WASTE NAME	GENERATION PROCESS	HAZARDOUS WASTE DÉTERMINATION	ESTIMATED GENERATION RATE	ON-SITE MANAGEMENT	OFF-SITE MANAGEMENT
served x as sho hezardo iversal	S Waste I spent 41 wn in pho us waste d	lazardous Waste Determinations (NOV #3C) - According to 10 CSR 25-5 bserved 11 spent 4ft lamps (not any low-mercury content green-tips) in storiox as shown in photos 6 and 7. Mr. Moran did not know exactly how long hazardous waste determination had not been made on the spent lamps. I diniversal waste if they are determined to be hazardous. He stated that he did	ing to 10 CSR 25-5.262 green-tips) in storage a exactly how long they be spent lamps. I discus e stated that he did not long	(1)-40 CFR 262.11, a haz if the time of the inspection. have been stored other than sed with Mr. Moran the cho mow if they wanted to hand	lazardous Waste Determinations (NOV #3C) - According to 10 CSR 25-5.262(1)→40 CFR 262.11, a hazardous waste determination is to be made on all solid waste. beserved 11 spent 4ft lamps (not any low-mercury content green-tips) in storage at the time of the inspection. They were being stored in an open, unlabeled and undated ox as shown in photos 6 and 7. Mr. Moran did not know exactly how long they have been stored other than they were generated during his three years at UPI-KCMO. Hazardous waste determination had not been made on the spent lamps. I discussed with Mr. Moran the choice of handling the spent lamps as hazardous waste or niversal waste.	e on all solid waste. abeled and undated ars at UPI-KCMO. dous waste or
o-general	ator of Sport with the	rent Lamps – Mr. Moran stated that h e electrician, he should ensure that a h	e did not know how the azardous waste determi	spent lamps taken by the el nation has been made on th	ogenerator of Spent Lamps - Mr. Moran stated that he did not know how the spent lamps taken by the electrician were being handled. I informed Mr. Moran that as a ogenerator with the electrician, he should ensure that a hazardous waste determination has been made on the Dispatch Office spent lamps and that they are being handled roperly.	d Mr. Moran that as hey are being handle
S S S S S S S S S S S S S S S S S S S	Floor Sweepings / Contaminated	Mr. Moran stated that they put floor dry The floor sweepings on the floor to collect all vehicle fluid without floor dry are spills in the process areas. He stated determined to be nor	The floor sweepings without floor dry are determined to be non-	The generation rate of the floor sweepings without floor dry varies,	The floor sweepings without floor dry are collected with the general trash (see waste without floor dry are stream #16).	The floor sweepings without floor dry are collected with the

The floor sweepings without floor dry are collected with the general trash (see waste stream #16). Mr. Moran stated that he has not shipped any contaminated floor dry off-site in his three years and he is not sur what was done with it prior to his time.
The floor sweepings without floor dry are collected with the general trash (see waste stream #16). The contaminated floor dry has not been generated to date as discussed below.
The generation rate of the floor sweepings without floor dry varies. Mr. Moran stated that they have not generated any contaminated floor dry since he has been on-site.
The floor sweepings without floor dry are defermined to be non-hazardous based on knowledge. Mr. Moran stated that he has not generated any contaminated floor dry to date.
Mr. Moran stated that they put floor dry The floor sweepings on the floor to collect all vehicle fluid spills in the process areas. He stated that they sweep the process areas that hazardous based on have floor dry separate from the areas that do not. The floor dry may be contaminated with any type of vehicle. Mr. Moran stated that fluid depending on what spills/leaks (see photos 9, II, 16, 38, 39, 40, 45, 46 any contaminated floor and 47). Mr. Moran stated that the floor sweepings generated when sweeping the areas without floor dry would contain only dirt. He stated that the floor sweepings would not have any free liquids and that they do not sweep
Floor Sweepings / Contaminated Floor Dry

816-457-6064

te is not sure

ast Management of the Contaminated Floor Dry - At the time of the inspection, I observed contaminated floor dry in various process areas on-site including the Tank rea and Crusher Area where the pulled motors are stored (see photos 38, 39 and 46). However, as stated above, Mr. Moran stated that any contaminated floor dry would However, Mr. Moran stated that he knows the previous General Manager generated some contaminated floor dry because he worked with the "EPA." Mr. Moran ated that he did not know all the details including the amount removed, how it was disposed, and where it was exactly removed from other than it was from both inside torage Area, Core Return Area, Rack Area and Crusher Area (see photos 9, 11, 16, 38, 39, 40, 45, 46 and 47). I observed significant amounts on the floor in the Rack of contain any free liquids when generated. Mr. Moran stated that he has not generated any contaminated floor dry since being the General Manager for the past three nd outside

T-422

P0012/0088 F

-795

ovided Mr. Moran with various MDNR hazardous waste and used oil related technical bulletins including Does Your Business Generate Hazardous Waste, Used Oil azardous Waste Determination Discussion - When any contaminated floor dry is generated, a hazardous waste/used oil determination will need to be made. I enerators, Used Oil Contaminated Waste, Used Oil Cleanup Packet - Contaminated Soil and Debris, and Used Oil Cleanup Checklist.

	05-10-'12 11:26 FROM-U
OFF-SITE MANAGEMENT	Mr. Moran was not sure where the drains discharged.
ON-SITE MANAGEMENT	Mr. Moran was not sure where the drains discharged.
ESTIMATED GENERATION RATE	Sure The amount of waste discharged through the drains was unknown.
HAZARDOUS WASTE DETERMINATION	Mr. Moran was not sure where the drains discharged (see discussion below).
GENERATION PROCESS	Mr. Moran stated that they have four drains. They were located as follows: outside the Sales Office, in the sealed Electrical Room, in the Ford storage yard, and on the west side of the entrance (see attachment 8A). I also observed a drain at the northeast door that Mr. Moran stated was filled in with concrete to seal it off (see attachment 8A).
# WASTE NAME	2 Spills / Drains
702	CA

NI Spills (NOV #1) - According to 10 CSR 25-11.279(2)(B)4.B, used oil must not be disposed of into the environment. According to 10 CSR 25-11.279(2)(C) -+40 CFR see attachment 8A and photos 18 through 37 and 48 through 50). Mr. Moran showed me a sample filter pad that they purchased and plan to install inside all the drains to re stored in the yard areas for customers to removed parts. On average about 30 scrap vehicles are pulled and replaced in the yard areas daily and vehicles remain in the ard areas about 60 to 90 days. I observed numerous apparent oil spills in the yard, including into the drains in the Ford storage yard and on the west side of the entrance 79.22(d), upon detection of a release of used oil to the environment, the release must be stopped, contained and cleaned up. As discussed in Section 4.2, scrap vehicles ppeared to drain off onto the ground as shown in the above photos. Mr. Moran stated that he believed the outside area on the north side was all concrete pad, but in the ast, millings were placed on top to fill in pad holes (see photos 30 through 33). I asked Mr. Moran when was the last time they cleaned any spills/leaks from the yard. le stated that he has not during his three years, but he believed the previous General Manager did once as explained in waste stream #11. He stated that the previous oundations, and part consists of gravel (see attachment 8B for soil and concrete areas as noted by Mr. Moran). The concrete pads were not contained and oil spills atch any debris, residual fluids that may make it to the drains. According to Mr. Moran, part of the yard consists of concrete pads from old demolished building reneral Manager would have only removed the top soil and put it in a 55-gallon drum, but he did not know any other information as stated in waste stream #11.

pills and Drain Discharges / Additional Information - As stated above, I observed apparent oil spills being drained into the drain in the Ford storage yard (see photos ontacting their corporate office to find out if they had a permit. However, he did not receive this information prior to my completing the inspection. I asked for this ischarged. Lasked if they had a storm water permit or if they were on combined sewers. He was not sure. During the inspection, Mr. Moran stated that he was 0 through 24) and the drain on the west side of the entrance near the motor heist (see photos 48 through 50). Mr. Moran was not sure where the drains exactly iformation to be provided and he agreed (see attachment 5).

rolls are collected by The spent rags/fowel rolls are collected in | The spent rags/fowel Cintas, Kansas City, MO for laundry. containers. The spent rags/towel rolls are generated at about 25 rolls/rags per month. rolls are faundered and The spent rags/towel are therefore RCRA exempt uses cloth rags to wipe grease/oil from employees use cloth roll towels to dry Mr. Moran stated that the Mechanic their hands after washing them from his hands. He stated that other general use on-site. Spent Rags / Towel Rolls

***************************************	5-10-'12 11:26 FROM-U- PICK IT	816-457-6064	T-422 F	0014/0088 F-795
OFF.SITE MANAGEMENT	Mercury Switches with the Ampules – The waste mercury switches containing the ampules are not shipped off-site. Ampules Removed – Mr. Moran was not sure where the mercury ampules were sent off-site (see discussion below).	Removing the American Ampules — The scrap switches after removing the ampules are collected with the scrap metal (see waste stream #9).	•	
ON-SITE MANAGEMENT	Mercury Switches with the Ampules – The waste mercury switches containing the ampules are collected in a 10-gallon tub in the Yard Office (see photos I and 2). Ampules Removed – The ampules removed are collected in a 1-gallon tub in the Yard Office (see photos 3 through 5). Scrap Switches After Removing the Ampules – Mr. Moran stated that the scrap switches left after removing the ampules are collected with the scrap metal			
ESTIMATED GENERATION RATE	Mercury Switches with the Ampules – Mr. Moran stated that the generation rate of the mercury switches with the ampules varies. He stated that the approximately three-fourths full 10-gallon tub currently in storage was generated during his three years as General Manager (see photo 1). Ampules Removed – Mr. Moran stated that they have only shipped one full	1-gallon tub of mercury ampules off-site about one and half years ago. At the time of the inspection, I observed one I-gallon tub that contained a small amount of ampules (see photo 4). Mr. Moran stated that this tub would have been started after the above tub was shipped. He stated that they last generated some ampules about six months.	Scrap Switches After Removing the Ampules – The generation rate of the waste mercury switches after removing the ampules is the same as those containing the ampoules above.	
HAZARDOUS WASTE DETERMINATION	Mercury Switches with the Ampules – A hazardous waste determination had not been made on the waste mercury switches with the ampules. Ampules Removed – A hazardous waste determination had not been made on the ampules removed.	The scrap switches after removing the ampules being reclaimed as a scrap metal are RCRA exempt.		
GENERATION PROCESS	Waste mercury switches are removed from the scrap vehicles. This includes from the hoods, trunks, etc. They are collected in a plastic tub in the Yard Office (see photos I and 2). Mr. Moran stated that when they have time, they remove the mercury ampules and collect them in a 1-gallon plastic tub in the Yard Office (see photos 3 through 5 and 51).			
WASTENAME	Waste Mercury Switches			

azardous Waste Determinations (NOV #1E)/Additional Information – According to 10 CSR 25-5.262(1)-+40 CFR 262.11, a hazardous waste determination is to be ade on all solid waste. A hazardous waste determination had not been made on the waste mercury switches with the ampules and the ampules removed. Mr. Moran ated that under the government's Cash for Clunkers program, the "ELVS" program was started. He stated that this was a program where in order for a company to ceive the clunkers, they had to send the waste mercury removed to a specific place. He stated that they shipped one 1-gallon tub to that specific place, however, he did at recall the name of the place. During the inspection, Mr. Moran could not locate any information on the ELVS program or where the ampules were sent. I asked for sy additional information UPI-KCMO had on the program and where the mercury ampules were sent. He stated that he would look for it. I asked Mr. Moran if they had ade a hazardous waste determination on the waste mercury switches and ampules and he stated "no." I also discussed with Mr. Moran the choice of handling the waste ercury switches and ampules as hazardous waste or universal waste if they are determined to be hazardous. He stated that he did not know if they wanted to handle them hazardous or universal waste, and that he wanted to talk with his corporate office before deciding.

isked Mr. Moran how they removed the ampules from the switches. He stated that they are removed in the Yard Office which is located next to his office, and is also here the switches are stored (see attachment &A and photo 51). Mr. Moran stated that they remove the ampules over the desk with no containment, no employees have sen trained on handling mercury or mercury emergencies, they do not monitor the room for OSHA mercury exposure, and they do not package the ampules with packing aterial to prevent breakage (see photos 1 through 5 and 51). I discussed with Mr. Moran that as universal wastes, removing the ampules would require additional quirements be met per 10 CSR 25-16.273(2)(B) \rightarrow 40 CFR 273.13(c)(2). They include removing the ampules over containment and in a in a well ventilated room that is onitored for OSHA mercury levels, training for an emergency, and packing the ampules with packing material to prevent breakage. Mr. Moran stated that they last moved ampules about six months ago, and it was done by an old manager that is no longer at UPI-KCMO. Also, I informed Mr. Moran that as universal waste, the mainers of mercury switches with the ampules and the removed ampules would have to be specifically labeled, the length of storage documented, and not be stored over year as required by 10 CSR 25-16.273 \rightarrow 40 CFR 273.14(d) and 273.15(a) and (c). I observed the containers of waste mercury switches and mercury ampules not ecifically labeled and not dated. Mr. Moran did not know how long the switches had been accumulated, but stated that it would have been within the approximately one id a half years since they last shipped the one container of ampules off-site. I completed a MDNR universal waste checklist which is included as attachment 3D.

Spent Personal Protective Equipment (PPE)	The type of PPE worn during processing includes hard hats, company provided jeans, shirts, safety vests, leather gloves, boots, glasses, and Kevlar sleeves. Mr. Moran stated that the shirts, pants and gloves become spent and would be contaminated with oil/grease.	The shirts and pants are laundered and are therefore, RCRA exempt. The spent gloves are determined to be non-hazardous based on knowledge.	About 100 shirts and pants are generated per week. About 15 pairs of gloves are generated per year.	The shirts and pants are collected in containers. The spent gloves are collected in containers with the general trash (see waste stream #16).	The shirts and pants are collected by Cintas, Kansas City, MO for laundry. The spent gloves are disposed with the general trash (see waste stream #16).
	Refuse, paper, etc. This includes trash from the offices and trash removed from scrap vehicles.	The general trash is determined to be non-hazardous based on knowledge (see discussion below).	10, 10-gallon trash cans weekly.	The general trash is collected in containers in the offices and in a pile near the Pop Hood Area (see photo 47). It is then added to the crushed vehicles to be taken to the shredder.	The general trash is collected with the ferrous scrap metal (see waste stream #9).

05-10-'12 11:27 FROM-U- PICK IT 816-457-6064 T-422 P0016/0088 F-795

HAZARDOUS
WASTE ESTIMATED
WASTE NAME GENERATION PROCESS DETERMINATION GENERATION RATE ON-SITE MANAGEMENT MANAGEMENT

azardous Waste Determination (NOV #3B) - According to 10 CSR 25-5.262(1) \(\to 40 CFR 262.11 \), a hazardous waste determination is to be made on all solid waste. A zardous waste determination had not been made on the waste pulled from the scrap vehicles. Mr. Moran stated that all the trash removed from scrap vehicles is returned the scrap vehicles after they have been crushed to be sent to the shredder. He stated that this would include the two waste piles I observed near the Pop Hood Area (see 100s 40 and 47). Mr. Moran stated that they do not put large amounts of trash in the crushed vehicles because the shredders would not like most of the weight they ceived to be non-metal. He stated that if they receive a large load of trash from a vehicle, such as a truck full of leaves and wood, then they would collect the trash in a mi-trailer and haul it to the Deffenbaugh sanitary landfill. He stated that however, having to take the trash to Deffenbaugh happens on "very rare occasions." He stated at they last took a load of trash to the sanitary landfill about one year ago. All other trash is sent with the crushed vehicles to the scrap metal shredder (see waste stream). I discussed with Mr. Moran that a hazardous waste determination needs to be made on all waste trash, and that any hazardous waste trash should not be sent to a etal recycler. At the time of the inspection, I observed two full five gallon pails that Mr. Moran stated were removed from a scrap vehicle around the "beginning of last sek" (i.e., around 1/30/2012). One of the pails was in poor condition and labeled used anti-freeze, and the other one was labeled as some type of finish as shown in 10to 12. Mr. Moran stated that he did not know what to do with these two pails, and that they needed to do a hazardous waste determination on them.

Other waste streams discussed included the following:

- Waste tires are collected in a pile near the Break Down Area. They are loaded into a trailer owned by ABC Tires, Kansas City, MO. ABC Tires collects the waste tires for recycling into playground material. UPI-KCMO has an MDNR Tire Dealer permit.
- Mop water is not generated on-site and no painting is conducted on-site.

Polychlorinated Biphenyl (PCB) Transformers

P0017/0088 F-795

UPI-KCMO is currently working with EPA on removing PCB containing transformers. At the request of Kent Johnson, EPA Counsel, I visually inspected the transformer area. Mr. Moran stated that there were two transformers on-site. He stated that Kansas City Power & Light (KCPL) had already removed one transformer and was in the process of removing the other that day, 2/10/2012. Mr. Moran stated that both transformers were located in the Electrical Room, and none had been stored outside. He stated that they did not have any PCB spills outside. Mr. Moran stated that the PCB spill an inspector observed was in a catch pan that had collected when a spigot on the transformer was opened. Mr. Moran stated that he inspects the pan and they have not had any leaks. Photos of the transformer area are shown in photos 41 through 44.

4.5. Other RCRA Issues

At the time of the inspection, I inspected the facility as a non-generator of known hazardous waste, used oil generator, used oil collection center and small quantity handler of universal waste. However, additional hazardous waste determinations need to be made that may affect the non-generator status determination. The other regulatory requirements that were reviewed are shown in attachments 3B through 3D, which consists of the compliance checklists. Other than the items noted above, no other apparent violations were noted in these areas. However, EPA may be reviewing my findings further after the inspection that may change or add to my findings.

Environmental Engineer Date: 3/2/12Dedriel L. Newsome

Attachments

Copy of Business Cards (I page) Multi-media Screening Checklist (2 pages)

Checklists

A. Entry / Exit Checklist (2 pages)B. MDNR Used Oil Generator (2 pages)C. Used Oil Collection Center (2 pages)

D. Universal Waste Small Quantity Handler (4 pages)

Confidentiality Notice (1 page) Document of Receipt (1 page)

NOV (1 page)

Company Information
A. UPI-KCMO (1 page) B. U-Pull-It (1 page)

Facility Layouts

B. Aerial Photo with Designated Dirt Areas (1 page)C. Aerial Photo With Photo Locations (1 page) A. Facility Layout (2 pages)

BPA RCRAInfo Sheet (1 page)

11. Anti-Freeze Information 10. Used Oil Shipping Document (1 page)

A. Anti-Freeze Recycling Company Info (4 pages)

B. Anti-Freeze Shipping Document (3 pages)C. Anti-freeze Sheet from the MDNR Preventing Pollution During Vehicle Salvage Guide (3 pages)

12. MDNR Managing Gasoline Dispenser Fuel Filters and Wastes Associated with the Operation of Fuel Dispensing Systems Fact Sheet (3 pages)

13. Rapid Recovery Invoice (1 page)14. Spent Lead-Acid Batteries Shipping Document (2 pages)

Photographs (27 pages / 51 photos) Photo Log (3 pages)

1. Did facility file a Ter II report with fire department, Local & State Emergency Planning Committee? Yes D No D Forward to EPCRA

Toolin (lead, mercury, or polycyclic aromatic compounds) at any time over the last 5 years? No KS (stop) Yes D Forward to EPCRA

3. Has the facility: If any box in question 3 is marked - Forward to EPCRA

a. Stored 2500 bs of ammonia D, 2100 bs of chlorine D, or 210,000 bs of an industrial chemical D, at any time over the last 2 years? D The Does the facility have any of filled electrical equipment. No II (stop) Yes II Forward to 750A and ask. Has facility tested oil filled section of the facility have any oil filled electrical equipment to determine PCB content; No III Yes Ya number containing PCBs greater than 50 ppm 4 and percent of all photo 50 A 1 photos 50 A 1 pho If yes, does the facility have an NPDES permit for these storm water discharges? Yes D No D Forward to CWA V MY UFC.

4. Did you see any wastewater discharges not identified by the facility? No D (stop) Yes D - Identify location, time, appearance of discharge: EMERGENCY PLANNING & COMMUNITY RIGHT TO KNOW ACT (EPCRA) & TOXIC SUBSTANCE CONTROL ACT (TSCA) 3. During rainfall events, can storm water carry pollutants from maintracturing, processing, storage, disposal, shipping and receiving areas, or from construction sites >1 acre, to storm sewers or surface water? No D (stop) Yes 15. 1. Does the facility discharge any wastewater to storin sewers, surface water, or the land? No D (stop) Yes X
If yes, are all wastewater discharges permitted? Yes D No D Forward to CWA CWS Urr. where \$150 km/s.

2. Does the facility have process wastewaters that are discharged to a city POTW (Publicly Owned Treatment Works)? No DX (stop) Yes D. CLEAN WATER ACT (CWA) - National Pollution Discharge Elimination System (NPDES), Industrial Pretreatment, Storm Water, & Wedands 1. Is the facility located in an apparent low income area (e.g., with many shandoned and dilapidated properties)? Does the facility have any wettand areas (e.g. streams, ponds, or temporarily wet areas)? No ED (stop) Yes CI d. Generated > one half pound of metal dusts, furnes, or metal turnings, over the last calendar year? If yes, is facility less then 1000 feet from nearest routinely occupied property (house, school, etc.)? No □ (stop) Yes □ Forward to EJ If yes, does the city have a state or EPA approved pretreatment program? Yes O No or Don't Know O Forward to CWA c. Used ≥10,000 lbs of aminonia □, chlorine □, halogenated solvents □, solvent-based paints □, or solvents □, or nitrated compound If yes, have any wettand areas been dredged, filled, channelized, dammed, or had gravel removed from them within the last 5 years? If yes, are the discharges permitted by: State? □, City? □ - If yes, Stop here. No □ Forward to CWA b. Stored >10,000 lbs of pressurized flammable material (propane, methane, butane, pentane, etc.) at any time over the last 2 years? I No ☐ (stop). Yes ☐ - Identity location and timeframe. (Get Photo) FWD to Wellands (Gut Photo) Forward to CWA 西口語が変し Toka sak

GRAY SHADED AREAS INDICATE ITEMS YOU NEED TO LOOK FOR DURING VISUAL INSPECTION

SEATH OF JUST OF J

ATTACHMENT 25...

Adam Moran
General Manager

(913) 207-7879

**Weskerfun89829yahoo.com
1142 South 12th St.
Kansas City, KS 68105
Kansas City, KS 68105
(818) 241-7548

;	05-10-'12 11:28 FROM-U- PICK	IT	816-457-6064	T-422 P0022/0088 F-795
Despitized that findings and observations are based on your current knowledge of RCRA and that the finel findings may differ a Bexplained that secompliance officers will make the final compliance decisions and that all compliance questions should be directed toward shem to the final compliance questions and that the finel formational purposes only and DO NOT require specific actions by the facility Dyferided facility with CB1 form 2) Specific information requested from facility? 2) Precific property to have avareness of RCRA regulations and/of has its own environmental staff? 3) Facility appears to have avareness of RCRA regulations and/of has its own environmental staff? 3) Property in the facility of applicable regulations? 4) Property in the facility of the facili	EXIT BRIDGING. 1. Reviewed all date collected and documented all concerns or violations? (The DNo - Location of the violation, type and amount of waste involved, time frame, frequency, specific dates & when first started occurred. - Diegal disposal - how, when (each occurrence), where sent or disposed of, how shipped, who shipped, when shipped/verified violations from previous inspection were corrected (if applicable). - Baydressed all unresolved inspection related issues - Boyletnessed findings and observations for the facility representatives - NOV issued? These DNo DViolations clearly identified and explained, including: circumstances, location, and applicable regulations - Proprietors to timely (14 day) and adequate response	UNO - Access decited Name of person denying sociess.	3. Does representative have intinute knowledge of all waste management practices? [Pres DNo How long in position?] 4. Introductions: 1. Intr	Daily Daily Ochabeted from public right-of-way? Determine the direction 'North' with respect to the facility and provide a brief ske of the layout and orientation (as can be viewed from the public right-of-way). Obvious concerns visible from public right-of-way (photos)? - Containers - Conta

	05-10-'12 11:28 FROM-U- PICK IT	816-457-6064	T-422 P0023/0088 F-795
B. Mixtures of used oil and hazardous waste are managed according to state hazardous waste regulations - 10 CSR 25-11.279(2)(B)2. B. ON-SITE BURNING 1. Burn only their own used oil or used oil from DiYers or exempt farmers - 10 CSR 25-11.279(1) incorporating 40 CFR 279.23(a) as amended by 10 CSR 25-11.279(2)(A)1. 2. Burn only in space heaters with design capacity < .5 million BTU/hr - 10 CSR 25-11.279(1) incorporating 40 CFR 279.23(b). 3. Combustion gases from the heater are vented to the ambient air - 10 CSR 25-11.279(1) incorporating 40 CFR 279.23(c).			MISSOURI DEPARTMENT OF NATURAL RESOURCES HAZARDOUS WASTE PROGRAM USED OIL GENERATOR NAME U-P;ck-I+ ADDRESS 7706 E. H J 24 CITY CIT
COMMENTS	COMMENTS		EPALD.NUMBER MOLD. NUMBER TELEPHONE NUMBER

	05-10-'12 11:28 FROM-U- PICK IT	816-457-6064	T-422 P0024/0088 F-795	HAMALANA JANANA
MSPECTOR'S SIGNATURE		Circle the it not in compliance and provide comment. N/A = Not Applicable. An item emphasized by a black line on the left is a serious deviation from the requirements (Class I Violation). An unemphasized item is a significant deviation from the requirements (Class II Violation unless conditions warrant Class COMMENTS	of the generator - 10 CSR 25-11.279(1) incorporating 40 CFR 279.24(a)(1). 3. Transports no more than 55 gallons of used oil at any time - 10 CSR 25-11.279(1) incorporating 40 CFR 279.24(a)(2). 4. Transports the used oil to a used oil collection center that is registered, licensed, permitted, or recognized by a state/county/municipal government to manage used oil - 10 CSR 25-11.279(1) incorporating 40 CFR 279.24(a)(3). OR 40 CFR 279.24(b) 5. Transports the used oil to an aggregation point that is owned and/or operated by the same generator - 10 CSR 25-11.279(1) incorporating 40 CFR 279.24(a)(3). OR 40 CFR 279.24(c) 6. Used oil is reclaimed under a contractual agreement (tolling arrangement) - 10 CSR 25-11.279(1) incorporating 40 CFR 279.24(c). CHECKLIST KEY Check the I in compliance.	C. OFF-SITE SHIPMENTS TO APPROVED COLLECTION CENTERS 1. Used oil is transported by transporters who have obtained EPA identification numbers unless one of the following is met - 10 CSR 25-11.279(1) incorporaling 40 CFR 279.24. 40 CFR 279.24(a) 2. U Transports used oil in a vehicle owned by the generator or owned by an employee
DATE		nts (Class I Violation). unless conditions warrant Class I).	13 9 6 6 8 25 Z	***************************************

05-10-'12 11:29 FROM-U- PICK IT 816-457-6064 T-422 P0025/0088 F-795 (NO-30) 1524 (NF ON) A. GENERAL REQUIREMENTS

| D Facility has notified the department of its used oil collection activities - 10 CSH 25-11-279(2)(D)2. B. USED DIL STORAGE **S** DESCRIPTION OF THE FACILITY'S OPERATIONS AND PLANT FACILITY REPAIRSENTATIVE(S), TITLE(S) 4. (3) Containers in good condition - 10 CSR 25-11.279(1) incorporating 40 CFR pot part 0 279.31(b)(1) referencing 40 CFR 279.22(b)(1). 2. Clean up any spills or leaks of used oil - 10 CSR 25-11.279(1) incorporating 40 CFR 279.31(b)(1) referencing 40 CFR 279.22(d). ှာ (၃) 3. We have means of controlling public access to the used oil storage area - 10 CSR 25-11.279(2)(D)5. Containers storing used oil are not leaking - 10 CSR 25-11.279(1) incorporating 40 CFR 279.31(b)(1) referencing 40 CFR 279.22(b)(2). ルーパートーゴオ Containers/aboveground tanks are labeled or marked clearly "Used OII" - 10 CSR 25-11.279(1) incorporating 40 CFR 279.31(b)(1) referencing 40 CFR 279.22(c)(1). No quantity of used oil stored for more than 12 months - 10 CSR 25-11.279(2)(D)3. Attendant present when the public has access to the facility - 10 CSR 25-11.279(2)(D)5.B. 7700 アルブの MISSOURI DEPARTMENT OF NATURAL RESOURCES HAZARDOUS WASTE PROGRAM

USED OIL COLLECTION CENTER INSPECTION RECORD AND CHECKLIST L.J HAK N 1 NUMBER OF EMPLOYEES 2/8-9/12 ALY SUFYER J COMMENTS COMMENTS Say C MO LO, NUMBER EXEMIONE NUMBER

05-10-12 11:29 FROM-U- PICK IT 816-457-6064 T-422 P0027/0088 F-795 34 3. [] N. PREPARE A SMALL QUANTITY HANDLER OF UNIVERSAL WASTE DOES NOT ACCUMULATE 5,000 KG OR MORE TOTAL OF ALL TYPES OF UNIVERSAL WASTE AT ANY TIME. WO 2002/129 (DI-11) ā ģ Ž. 1.0 فدا スル GENERAL 7780 III W.P.J. **(2)** Q A 200 MISSOURI DEPARTMENT OF NATURAL RESOURCES
HAZARDOUS WASTE PROGRAM
UNIVERSAL WASTE SMALL QUANTITY HANDLER CHECKLIST procedures appropriate for universal wastes handled at the facility – 10 CSR 25-16.273(1) incorporating 40 CFR 273.16 handlers unless operating a universal waste pesticide collection program – 10 CSR 25-16.273(2)(B)1.

Universal waste accumulated for less than one year from the date generated or received from another handler – 10 CSR 25-18.273(1) incorporating 40 CFR 273.15(a). Complies with universal waste transporter requirements if self transporting universal waste - 10 CSR 25-16.273(1) incorporating 40 CFR 273.18(b). resource recovery facility, or foreign destination - 10 CSR 25-16.273(1) incorporating 40 CFR 273.18(a) as modified by Determines if materials from a universal waste release are hazardous waste and are properly managed – 10 CSR 25-16.273(1) incorporating 40 CFR 273.17(b). Accumulates universal waste for only one year unless able to demonstrate activity is solely for the purpose of accumulating quantities to facilitate proper recovery, treatment or disposal – 10 CSR 25-16.273(1) incorporating been accumulated from the date it becomes a waste or is received (marking, labeling, inventory, dated area, or other valid method) -- 10 CSR 25-16.273(1) incorporating 40 CFR Does not dilute or treat universal waste except as provided by 40 CFR 273.17 or 40 CFR 273.13 – 10 CSR 25-16.273(1) incorporating 40 CFR 273.11(b). and provides placards per DOT requirements on universal waste that meets hazardous materials definition – 10 CSR 25-16.273(1) incorporating 40 CFR 273.18(c). information describing proper handling and emergency Immediately contains all releases of universal wastes and universal waste residues – 10 CSR 25-16.273(1) incorporating 40 CFR 273.17(a). Does not dispose of universal waste - 10 CSR 25-16.273(1) incorporating 40 CFR 273.11(a). Ensures receiving handler agrees to accept universal waste prior to shipment – 10 CSR 25-16.273(1) incorporating 40 CFR 273.18(d). Non-pesticide universal wastes only sent to another universal waste handler, destination facility, Missouri Can demonstrate the length of time universal waste has Does not accept universal waste pesticides from other Uses proper shipping documents, packages, labels, marks Provides all employees who manage universal waste with 10 CSR 25-16.273(2)(B) #w# かっ STULI LOWINGS N õ ELEPHONE NUMBER WITH AREA CODE No stay る。これ -------N N N ڪيت ands. N 143 N Secrapord NA Ž su rest 2 Name of RR NUMBER NUMBER OF EMPLOYEES Univopiesse known paries. COMMENTS DATE OF LAST INSPECTION Ŋ

*1.2.E	
2 2	
TANKER SDEAN PARK	
*	

MO 780-2129 (01-11)

O. OFF-SITES	O. OFF-SITE SHIPMENTS (CONTINUED) Accepts rejected universal waste or agrees with receiving		COMMENTS
	handler to ship to an alternate destination facility 10 CSR 25-16.273(1) incorporating 40 CFR 273.18(e).	N	A CONTRACTOR OF THE PARTY OF TH
ŝ. G. Q.	Contacts originating handler to discuss reshipment of the load back to originating handler or to a multivally agreed on destination facility if handler rejects a shipment or portion of a shipment – 10 CSR 25-16.273(1) incorporating 40 CFR 273.18(f).	N	ener ener
7.000	Originating handler receives back or sends rejected posticides to another Missouri-certified resource recovery facility or destination facility if universal waste pesticides are rejected - 10 CSR 25-16-273(2)(B)4.	, Na	**************************************
	Immediately notifies the department if receive a shipment of hazardous waste and provides required information – 10 CSR 25-16.273(1) incorporating 40 CFR 273.18(g).	N	1
	Manages waste in compliance with applicable solid waste regulations if receives a shipment of non-hazardous, non-universal wastes — 10 CSR 25-16.273(1) incorporating 40 CFR 273.18(h).	N	STA ONLY
	Exported universal waste regulations met including notification, annual reporting, and record keeping – 10 CSR 25-16.273(1) incorporating 40 CFR 273.20 referencing 40 CFR 262 Subpart E or Subpart H.	2	No or Served
P. BATTERIES			COMMENTS
	Batteries stored in a manner to prevent releases to the environment (box, shrink wrapped pallet, container, etc) – 10 CSR 25-16.273(1) incorporating 40 CFR 273.13(a).	N	, E
	Damaged or leaking batteries kept in closed, structurally sound containers – 10 CSR 25-16.273(1) incorporating 40 CFR 273.13(a)(1).	ands.	a diament
3,000	Individual battery cells kept intact and closed while performing approved management of batteries (sorting, discharging, disassembling battery packs, etc) – 10 CSR 25-16.273(1) incorporating 40 CFR273.13(a)(2).	N	
	Cells immediately closed after the removal of electrolyte – 10 CSR 25-16.273(1) incorporating 40 CFR273.13(a)(2).		·
	If casings of individual battery cells are breached then manages batteries as hazardous waste if characteristic – 10 CSR 25-5.262(1) incorporating 40 CFR 262.11.		Q. 7.
	Determines if electrolyte removed from cells and other solid wastes generated exhibit hazardous waste characteristics and properly manages wastes – 10 CSR 25-16.273(1) incorporating 40 CFR 273.13(3).		and keep
	Batteries or battery containers clearly labeled or marked as "Universal Waste-Battery(ies)" or "Waste Battery(ies)" or "Used Battery(ies)" ~ 10 CSR 25-16.273(1) incorporating 40 CFR 273.14(a).	N	*10 S
O. PESTICIDES	that have been recalled or are unused and nathered as a Misso		COMMENTS COMMENTS
Only pesticides be mainaged as	Only pesticides that have been recalled or are unused and gathered as a Missouri authorized waste pesticide collection program can be managed as universal wastes.	8	thorized waste pesticide colle
	Universal waste pesticides stored in closed, structurally sound container that is compatible with the wastes and not leaking or damaged – 10 CSR 25-16.273(1) incorporating 40 CFR 273.13(b)(1).		NX
	Universal waste pesticides stored in closed, structurally sound transport vehicles/vessels that are compatible with the wastes and not leaking or damaged –10 CSR 25-16.273(1) incorporating 40 CFR 273.13(b)(4).		
	Universal waste pesticide stored in tanks that conform with Part 265 Subpart J except for 40 CFR 265.197(c), 265.200, and 265.201 – 10 CSR 25-16.273(1) incorporating 40 CFR 273.13(b)(3).	WANTE TO SERVICE THE PARTY OF T	

E T	ah:	Open original housing holding mercury removed from mercury containing equipment immediately sealed with airtight seal – 10 CSR 25-16.273(1) incorporating 40 CFR 273.13(c)(3)(i).	ë G G
	Name of the last o	Removed ampules or open original housing holding mercury stored in closed, non leaking containers that are in good condition and packaged with adequate packing material to prevent breakage during storage, handling, and transportation – 10 CSR 25-16.273(1) incorporating 40 CFR 273, 13(c)(2)(vii).	8.0
	N	Employees removing ampules or open original housing holding mercury thoroughly familiar with proper mercury handling and emergency procedure – 10 CSR 25-16.273(1) incorporating 40 CFR 273.13(c)(2)(vi).	7.00
	Ŋ	Area where ampules or open original housing holding mercury are removed is well ventilated and monitored to ensure compliance with applicable OSHA exposure levels of mercury – 10 CSR 25-16.273(1) incorporating 40 CFR 273.13(c)(2)(v) and 273.33(c)(2).	8.0 0 0
20 x 1/1/2 065		Mercury from spills or leaks of broken ampules or open original housing holding mercury immediately transferred to container meeting 40 CFR 262.34 requirements – 10 CSR 25-16.273(1) incorporating 40 CFR 273.13(c)(2)(iv).	5.000
	N	Mercury clean-up system readily available ~ 10 CSR 25- 16.273(1) incorporating 40 CFR 273.13(c)(2)(iii).	
The later	.	Mercury ampules or open original housing holding mercury removed over or in a containment device – 10 CSR 25-16.273(1) incorporating 40 CFR 273.13(c)(2)(II).	3.0 0 0
		Damaged or leaking mercury containing equipment or mercury containing equipment with non-contained elemental mercury kept in a closed, structurally sound container – 10 CSR 25-16.273(1) incorporating 40 CFR 273.13(c)(1).	2 6 00
		Mercury containing equipment stored in a manner to prevent releases to the environment (box, container, etc.) – 10 CSR 25-16.273(1) incorporating 40 CFR 273.13(c).	1.600
COMMENTS		R. MERCURY CONTAINING EQUIPMENT	R. MERCURY C
allerioneer		Universal waste pesticides not sent to or received from another universal waste handler - 10 CSR 25-16.273(2)(B).	å O O
		Universal waste pesticides sent only to authorized destination facility or Missouri universal waste pesticide program – 10 CSR 25-16.273(2)(B).	
	N	Universal waste pesticides container, tank, transport vehicle or vessel marked or labeled clearly with product label and the words "Universal Waste Pesticide(s)" or "Waste Pesticide(s)" – 10 CSR 25-16.273(1) incorporating 40 CFR 273.14(b)(2) and (c)(2).	٥٥٥٥
7	N	Unused universal waste pesticide container, tank, transport vehicle or vessel labeled or marked with the label that was on or accompanied the product as sold/distributed or the US DOT label as required by 49 CFR Part 172, or a label designated by the Missouri waste pesticide collection program – 10 CSR 25-16.273(1) incorporating 40 CFR 273.14(c)(1).	5.000
	N	Recalled universal waste pesticide container, tank, transport vehicle or vessel labeled or marked with the label that was on or accompanied the product as sold/distributed — 10 CSR 25-16.273(1) incorporating 40 CFR 273.14(b)(1).	â G G
COMMENTS		(CONTINUED)	Q. PESTICIDES (CONTINUED)

				ACCRECATION OF THE PROPERTY OF					former.
		3 □ 🔞 🗆	2.000	1000	S. LAMPS	12. 🗆 🗛 🗹	11.0 @0	10. 🗆 🗖	R. MERCURY C
273.14(e)	Each lamp or lamp container or package marked or labeled dearly as "Universal Waste Lamp(s)" or "Waste Lamp(s)" or "Used Lamps" – 10 CSR 25-16.273(1) incorporating 40 CFR	Unbroken lamps stored in closed, non-leaking containers or packages that are structurally sound and adequate to prevent breakage – 10 CSR 25-15.273(1) incorporating 40 CFR 273,13(d)(1).	Bulb crusher or other type of treatment not performed on lamps - Section 260,390,1(1) RSMo.	Broken or leaking lamps immediately cleanup and placed in closed, structurally sound, non-leaking containers and managed as hazardous waste – 10 CSR 25-16.273(1) incorporating 40 CFR 273.13(d)(2) and 10 CSR 25-5.262(1) incorporating 40 CFR 262.11.		Universal waste mercury containing thermostats or containers marked or labeled as "Universal Waste-Mercury Thermostat(s)" "Waste Mercury Thermostat(s)" or "Used Mercury Thermostat(s)" – 10 CSR 25-15.273(1) incorporating 40 CFR 273.14(d)(2).	Universal waste mercury equipment or containers marked or labeled clearly. 'Universal Waste-Mercury Containing Equipment' or "Waste Mercury Containing Equipment" or "Used Mercury Containing Equipment" – 10 CSR 25-16.273(1) incorporating 40 CFR 273.14(d)(1).	Determines if wastes generated from mercury amputes or housing removal activities exhibits hazardous waste characteristics. If hazardous waste then manages as hazardous waste per 40 CFR part 262 – 10 CSR 25-16.273(1) incorporating 40 CFR 273.13(c)(4).	R. MERCURY CONTAINING EQUIPMENT (CONTINUED)
	Ŋ	2	, x	».		2	N		
					COMMENTS			Day March	COMMENTS

Information for which confidential treatment is requested:

(Rev: 11/15/99)

Maries of

816-457-6064

Hacility Address 7700 E. Winner Rd. Kayisas City Mo Inspector (print)	
U.S. EPA, Region VII, 901 N. 5th St., Kansas City, KS 66101	Date
onmental Protection Agency (EPA) is obligated.	
The United States Environmental Protection Agency (EPA) is obligated, under the Freedom of Information Act, to release information collected during inspections to persons who submit requests for that information. The Fr	
of Information Act does, however, have provisions that allow EPA to withhold certain confidential business	under the Freedom of Info ut requests for that inform

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY CONFIDENTIALITY NOTICE

A Char rectorn

- Your company has taken measures to protect the confidentiality of the information, and it intends to continue to take such measures.
- No statute specifically requires disclosure of the information.
- Disclosure of the information would cause substantial harm to your company's competitive position.

ţ

Information that you claim confidential will be held as such pending a determination of applicability by EPA.

I have received this Notice and DQ want to make a claim of confidentiality. Facility Representative Provided Notice (print) Signature/Date
--

7

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY RECEIPT FOR DOCUMENTS AND SAMPLES

Notice of Violation Pursuant to Requirements of the Resource Conservation and Recovery Act (RCRA)


Printed Name: A Date: Signature:	If you have any questions about this Notice or wish to discuss your response, you may call me at 1/3-55/-16-73	You are requested to submit a written response within 14 calendar days of receipt of this notice. Your response should include a description of all corrective actions taken and/or a schedule for completing the necessary corrective actions. The response should be submitted to: U. S. Environmental Protection Agency, Region VII On Str. Str. Str. Str. Str. Str. Str. Str.	Make a hozarbase suite determination on NS unknown drums De Stad pails of unknown (truck removed from cars) C) Spent lamps A) Gastline filters in constituent	Description of Violation Description of Violation	TO: Facility Name: 1/2 Pick - 12-4 Address: 7700 E. 100, Area Rol EPA ID Number: Non- provided to Call your attention to the following areas of noncompliance with state and federal regulations. This notice does not constitute a compliance order (Administrative Civil Complaint) pursuant to Section 3008 of RCRA and may not be a complete listing of all violations resulting from the the inspection.
----------------------------------	---	---	---	--	--


816-457-6064

T-422 P0033/0088 F-795

05-10-'12 11:30 FROM-U- PICK IT

Attachment 6 Page of The





We Buy Unwanted & Junk

click here to sell your vehicle **816-241-7548**


U-pick-it - pick what you want from our yard for the best deal on used auto parts!!!

We are open now!!!

Hours of operation

Winter hours now in effect
8:00am till 5:00pm Mon-Fri
8:00am till 5:00pm Saturday
9:00am till 5:00pm Sunday

please check back frequently for updates and to see new listings of vehicles in our yard



> 5




Always Buying Junk Cars and Scrap Metal

Page I of I

click here to sell your vehicle

402-342-0831 402-734-6029




Sell Your Vehicle

Contact Us Locations

8:00am till 7:00pm Mon-Sunday Hours of operation We close at Dark Winter Hours

please check back frequently for updates to our site



18. S. S.


South Yard


ton Cash for Now Michael Charley Corn Your Carto Charly

つうしょういいつ

ATTACHMENT B.


S10-1-3800/98004 22-1-35 A Page 1 of 2009-124-918






ATTACHMENT 84 Page 2 of 2

| 1 ~ ~ 816-457-6064 U PickIt KC, MO Layout
with some photo becations
2/9-10/12 FCRA IN SPECTION # = photo # and direction






Page 2 of 3




Bird's eye view maps can't be printed, so another map view has been substituted.

ATTACHMENT & PPage 2 of 2



Page | of 1



05-10-'12 11:32 FROM-U- PICK IT 816-457-6064 T-422 GAL 30 GAL 85 GAL 1910MER/9HIPPER: U-PICK-17
1910MER/9HIPPER: U-PI W6# CODE VARHER: HERITAGE-CRYSTAL CLEAN, LLC JOTOMERIGHIPPER: U-PICK-IT 7700 E. WINNER KANSAS CITY, MO 64125 MO Flex. 3/10 Frimed in USA GENERAL CLEAN, LLC DRK ORDER ALD SEM PRODUCT DESCRIPTION: used oil ean, Sta 00000000 FF**F**** 3/05/2 60#80#8#### TE UNIT OF INNER THE OF THE MAN- NOT RESIDEATED, (DEND OIL), A XIETRI GIST 00 2004 HRBB pick of DESCRIPTION COCHACT CON #A CONTROL N KANSAS CITY - OIL 1-1 TRUCK 2 00-004HRBB 205847 (913)207-3281 GALS. SH NO. EPA ID #: ILR 000 130 062 MINITO SE CHANGE PROPER SHPPING MARK SERVICE/PRODUCTS CHARGE SUMMARY
115 10 SEPTEMBERS AND THAT SAID SERVICES AND THE CHARGES
125 TELEFORMED AND THAT SAID SERVICES AND THE CHARGES
125 TELEFORMED AND THAT SAID SERVICES AND THE CHARGES
125 TELEFORMER TO THE CHARGE SUMMARY
125 TELEFORMER TO THE CHARGE SUMMARY CUSTOMER PHODUCIS 10 DESTINATION: HENTAGE-CRYSTAL CLEAN, LLC 1401 FAINFAX TRAFFICWAY BUILDING C - 201 KANSAS CITY, KS 46115 Phone Number: (913)233-2651 ď 霧鷹 **3** 5 5 CESQG 120111 COMMENTS. 531575 THIS IS NOT AN INVOICE **△**,25 SUBJODNICT SALESTAX Phone Number (877) 938-7948 CLA-4 TARANTTARAN 7/0-1 PRODUCT & TAX
TOTAL AMOUNT DUE
TOTAL REMITTANCE
CHECK NUMBER SERVICE SUBTOTAL TODAY'S SERVICE PROMI PHICE FEDERAL EMAID # STATE EPAID # 313 97 S WOULD Digital Park CHAPTOR 2 CHARGE 8

1-16-1997 4:4344

FROM HI TECH ANTIFREEZE 7866421230

Hi-Tech Antifreeze
Recycling/PghGeniLLC.
Box 230, 530 Main
Budora, KS. 66025

785-542-1230) fax 785-542-1230 e-mail: anultr-exagaiin: flower.com

Robert

I am sending you the following information about our antifreeze business. Please visit our website: www.recyclingantifreeze.com. Call the phone number or e-mail above if we can be of service to you or if you have any questions.

Fig. Tech Antifreeze provides a 50/50 pre-mix, ready-to-use, recycled coolant at less boat than recycling yourself or buying virgin antifreeze and mixing with water. Hitech also provides virgin antifreeze, full strength or 50/50 premix. Call us for current prices. Let us know when your barrel is empty and we will fill it as soon as possible. Our trucks are equipped with certified flow meters that stamp your ticket showing the number of gallons delivered. This eliminates guessing on bulk delivaries.

Hi-Tech will also remove waste antifreeze at no charge whether you buy coolant or not. Call us when your waste barrel is full (minimum 50 gallons). The driver will pump out the waste barrel and leave this area as clean as he found it. Barrels or tanks will be properly labeled to meet regulations.

If you need barrels, we have opaque white (so you can see the level inside) 55 gallon drums, our/your cost is \$20.00 and 275 gallon totes (call for price). Also, the drivers have a rotary hand barrel pump for our/your cost of \$20.00.

Hi-Tech provides great service and quality products saving you time and money.

Hi-Tech Antifreeze Recycling/Pgh Geni LLC operates in compliance with all city, state and federal regulations pertaining to recycled coolant (Permit #873).

Additional information provided upon request.

Thank you,

Richard Campbell

Thanks, Marily

V

ATTACHMENT III Dans 2 at 4

used antifreeze? How do you dispose of

free of charge. your used antifreeze We will pick up Answer: Call us.

coolant from us (call for pricing). purchase virgin quality recycled used coolant. You can also provide barrels or totes to collect to receive free pickup. We will not have to purchase coolant coolant for free, and you do Hi-Tech will pick up your used

recycling is done at the plant. has built a new facility and all improve this process. Hi-Tech combinations and additives to processes as well as chemical researches and explores alternative Tech's management continually a one-man operation. Hifounded in 1991, began as Hi-Tech Antifreeze Recycling,

> RECYCLING HI-TECH ANTIFREEZE

身份的人自然的實質和實質的關係的學的學科學

ENDORA, KS ANTI-FART

antifreeze@sunflower.com E-Mail:

product. and approved virgin quality The result is a laboratory tested

duty (wet sleeve diesels). orange, universal gold and heavy automotive green, extended life makes four types of coolane: coolant. Currently Hi-Tech then added to make virgin quality The appropriate inhibitors are of ethylene glycol and water. produces a clear liquid consisting contaminates, including dye and Hi-Tech's process removes

disappointed. sell is service, you will not be product but what we really We make and provide a quality

(call about other areas). Missouri and Nebraska We provide service in Kansas, regulations (permit #873). with all city, state and federal Hi-Tech operates in compliance

05-10-'12 11:32 FROM-U- PICK IT

816-457-6064

T-422 P0044/0088 F-795

05-10-'12 11:32 FROM-U- PICK IT 816-457-6064 T-422 P0045/0088 F-795 785 841-7444 THE PRICES OF MICHANICE LETTED BELOW HAVE BEEN SQUED TO THE HISTORY ABOVE FOR THE POLICY PERIOD PRICATED, NOTWITHSTANDING ANY PERIODS. THE MICHAEL BETT WAY OF STREET ON OTHER DOCUMENT WITH RESPECT TO WHICH THIS CONTROL MAY IS INSUED OF SUCH MAY PERIODS. AND CONTROL BY THE POLICY DESCRIPTION OF SUCH MAY PERIODS. AND CONTROL OF SUCH MAY PERIODS. AND CONTROL OF SUCH MICHAEL AND PROCESS AND PARTICIPAL STREET OF SUCH MICHAEL BY THE RESPONSION OF SUCH MICHAEL BY THE POLICY PERIODS. AND CONTROLS OF SUCH MICHAEL BY THE POLICY PERIODS. AND CONTROLS OF SUCH MICHAEL BY THE POLICY PERIODS AND CONTROLS OF SUCH MICHAEL BY THE POLICY PERIODS. AND CONTROLS OF SUCH PERIODS. 7,8;5; /807 /77/6n PARM SCHEAU FINANCIAL SERVICE 2201 M 25th Suite S 1-10-1997 4:45AM * ACORD. CERTIFICATE OF LIABILITY INSURANCE
9/12/2007
100 CERTIFICATE OF LIABILITY INSURANCE
9/12/2007
100 CERTIFICATE OF LIABILITY INSURANCE SYSTEM OF MORNING OF MORN CENTRICALE HOUSE ACCORD DE CORO SE MIDITOR PROMOT OFFICE TO BE COOKED AND THE CONTRACT OF COMMENCAL CONTROL X COCUM X POLOT BY THE SAME THE PROPERTY OF A THE PROPERTY OF THE PARTY OF HI-THER ANTIPHERE RECYCLING/ PINISPING GENT, LLC 530 MAIN, BOX 230 REDORA, NA. 56025 SCHOOL DEATHS NAME OF STREET SEA SEA WOMED WITH 8 SUNCERNO FOR MINA THEORY EMPLYING DEPARTMENT OF MASTE 1000 SM JACKSON, SUITE 320 STATE OF S 1858419548 55.61.2 FROM HI TECH ANTIFREEZE 7855421230 3 15115 -09/16/07 MODEL S. GLOTT VYWINE SMERTSH FARM BUREAU CANCELLATION.

PROLED HAY OF THE MOVE DESCRIBED POLICES OF CHARLESS MODERN THE EXPONITION BY THE PROPERTY WAS RESIDENT WAS DESCRIBE WAS DESCRIBED TO THE LETT, BUT FAILURE TO BO SO SHALL MAYOR TO DESCRIBE TO DESCRIBE TO BO DESCRIBE TO Tyland ollundary ذم 80/81/60 Č. CONVENSAL. Tabout Sent Lief MONTH DAMES WILDOW'S WAS COMMI ET BYCHYCODON CH COCAMBINICS PRINCE STATES PAGE 82/82

E C

Q ω

ATTACHMENT 16 Page 1 of 3

F6-Tech Antifreeze P.O. Box 230 Endors, KS 66625 (765) 542-1230 www.recyclingeetin II WILL ALIMNA 75:167 27 Colon Heading - State | 1884 used 308 E U- Pick IT 7700 E. 24 Huy Independence mo Picked up 825-9dic 5080-7C5-8TQ used-AFC We

Please Pay From This Invoice No Statement Will be Sent

Anti-Freeze

ATTACHMENT 116Page 2013

HI-Tech Antimedia P.D. Box 290 Eudora, K8 66825 (785) 542-1230 www.racydingahilireszs.com 11 WILL -D-WW1 76:167 71 -CG-78 Anti-Process Chape Cisco 810-457-b809 Please Pay From This Invoice No Statement Will be Scot

T-078 P0003/0000 F-073


ATTACHMENT IID Page 3 of 3

7-28-11 Se Ser Galor Foods
South C. Pick-IT
7700 E. 24 Houy U FILM II Independence mo. Pickel 4P 175-9 d's Usad-AFC Mana-10%-019 WE. Please Pay From This Invoice No Statement Will be Sent T-WIE FEMANZ/MMM4 E-WI3

Ami- Preces

C Recycled Paper

Preventing Pollution During Vehicle Salvage



Pollution Prevention for Vehicle Salvage Facilities in Missouri A Guide to Environmental Compliance and



Missouri Department of Natural Resources Environmental Assistance Office 1-800-361-4827

September 2004





Missouri Department of Natural Resources "integrity and excellence in all we do"

Antifreeze

glycol is toxic if ingested. It is particularly dangerous because animals and children are attracted to its sweet flavor. If they drink the ethylene glycol it may cause coma or death. Antifreeze is usually made of ethylene glycol, corrosion inhibitors and foam controllers. Ethylene

animals than ethylene glycol Some antifreeze is made of propylene glycol. This material is less hazardous to humans and

The used antifreeze from a vehicle can hold contaminants that it has picked up from the vehicle engine. For example, used antifreeze may contain lead because the antifreeze has dissolved some of the lead solder in the radiator.

regulations. However, it may be a hazardous waste depending on the contaminants it has Waste antifreeze is not a listed hazardous waste under the federal hazardous waste picked up. The test used to find out if used antifreeze is a hazardous waste is called the toxicity characteristic leaching procedure (TCLP). See the Hazardous Wastes guide sheet for more

antifreeze is more likely to be hazardous if it was used in heavy equipment such as buildozers and buses. hazardous waste. This is primarily because less lead is used in radiator construction. Used Recent studies have shown that antifreeze from cars and trucks manufactured after 1995 is not

antifreeze or with other hazardous wastes does not need to be tested. In this case, you may assume that it is not hazardous and need not test it. However, used antifreeze from heavy have some other way of knowing that it is or is not hazardous. equipment or industrial sources will need to be tested to see if it is hazardous waste unless you This means that antifreeze from late-model cars and trucks that has not been mixed with other

testing it. You would then need to dispose of it as hazardous waste. If you wish, you can assume the antifreeze from your heavy equipment is hazardous without

There are several ways to safely and legally manage your used antifreeze:

- Recycle the antifreeze at your facility (on-site recycling).
- Send the antifreeze to someone else to either recycle or dispose of it (off-site recycling or
- Discharge to public wastewater treatment plant if the plant has approved the discharge.

can purchase or lease several types of antifreeze recycling equipment. If you want to recycle your hazardous waste antifreeze on-site you must notify the department of your recycling The Missouri Department of Natural Resources strongly encourages antitreeze recycling. You

T-422 P0052/0088 F-795

> activities. If you recycle 2,200 lbs. or more in a month, you need a resource recovery certification. For more information, contact the department at 1-800-361-4827. If you recycle anlifreeze only from late-model cars and trucks, you do not need a resource

determine if these wastes are hazardous before disposal. See the Hazardous Waste guide your regular trash. However, liquids cannot go to the landfill. sheet for more information. If the residue is nonhazardous, it can be sent to the landfill with Your recycling unit will create waste such as distillation residues or used filters. You must

companies will need resource recovery certification to recycle your antifreeze. on-site. Again, if the antifreeze is from late model cars and trucks, these companies do not need resource recovery certification. If it is from heavy equipment or older cars, these There may be businesses that will bring equipment to your facility and recycle your antifreeze

Off-site Recycling or Disposal

facility you send it to has a resource recovery certification or a hazardous waste treatment, antifreeze is a hazardous waste, the transporter must have a Missouri license to transport storage and disposal permit. hazardous waste and the waste must have a hazardous waste manifest with it. Make sure the There are companies that pick up used antifreeze for off-site recycling or disposal. If your used

Discharge to wastewater treatment plant (pouring it down the drain)

down the drain is called a discharge. able to pour antifreeze down the drain IF you have permission from the plant. Pouring wastes If the drains at your facility go to a wastewater treatment plant (not a septic system), you may be

Some plants will not allow discharges of used antifreeze. Large quantities can harm the treatment plant. The wastewater treatment plant may not be able to remove all the contaminants from the used antifreeze. The contaminants then enter lakes, streams and rivers.

Remember

- DO NOT discharge antifreeze to a wastewater plant without permission.
- DO NOT discharge any hazardous waste, including antifreeze, to a septic system.
- DO NOT dispose of antifreeze on the ground, down storm drains or into streams or lakes.

Missouri Department of Natural Resources For More Information

www.dnr.mo.gov/oac/env assistance.htm 1-800-361-4827 or (573) 526-6627 Jefferson City, MO 65102-0176 Environmental Assistance Office

ATTACHMENT II Page 3 of 3



4 (Missouri Department of Natural Resources

and Wastes Associated with the Operation Managing Gasoline Dispenser Fuel Filters of Fuel Dispensing Systems

Hazardous Waste Program fact sheet

10/2009

spills. This guidance does not pertain to the management of petroleum debris and media that is subject to 40 CFR part 280 subparts E and F. and legally managing used gasoline dispenser fuel filters and other media impacted by gasoline ways that can lead to fires and explosions. The following guidance provides options for safely and the environment. Sometimes these wastes are illegally thrown into dumpsters or stored in absorbent materials, water and debris, can be toxic, ignitable and hazardous to people, property Used gasoline dispenser fuel filters and other fuel dispensing system wastes, such as

or other waste stored in the sump containment beneath the dispenser. During an inspection, the violation typically cited in the Missouri Secretary of States Code of State Regulations as Common Problem The Missouri Department of Agriculture's most issued violation is gasoline dispenser fuel filters 2 CSR 90-30:

secondary containment facility shall be removed and disposed of in a manner that is in this includes dikes and remote impoundments. Accumulated water and/or product within a "Water or product shall not be allowed to accumulate within any secondary containment facility, compliance with applicable rules of the Department of Natural Resources."

hold gasoline product in the event of a release, any material stored in the sump containment may not be stored or dried in the sump containment. The sump containment is designed to Gasoline dispenser fuel filters, absorbents or any other materials, including gasoline waste, reduces its capacity. The sump containment is intended only for abnormal operating conditions or emergency use. Storing gasoline dispenser fuel filters in the sump containment is also a fire hazard. Equipment in the dispenser can spark, igniting gasoline vapors and can cause a fire

Proper management of used gasoline dispenser fuel filters

Scrap Metal Option Metal gasoline dispenser fuel filters can be managed as scrap metal if the filters are drained of all liquids and the filters are sent for legitimate metal recycling.

container. The container should be labeled "scrap metal - gasoline dispenser fuel filters" and be Once drained and dried, metal gasoline tank dispenser filters should be stored in a closed sent to a scrap metal recycler with whom you have a written agreement and has the equipment you regularly contact your recycler to evaluate if scrap metal is being properly managed. to manage this type of metal and material. The Department of Natural Resources recommends

PUB2364

Recycled Paper

ATTACHMENT 12 Page 1 of 3

T-422 P0054/0088 F-795

Hazardous Waste Option

considered an exempt scrap metal when drained and sent to a legitimate metal recycler. hazardous waste and they meet no other exemption. Gasoline dispenser fuel filters may only be considered hazardous waste since they are likely to contain enough benzene to be a toxic Gasoline dispenser fuel filters and other related materials not destined for recycling should be

dry, but stored under high-heat conditions, they may spontaneously combust. liquid, gasoline dispenser fuel filters are typically hazardous waste due to ignitability. If they are unless representative sampling demonstrates the wastes are not hazardous. If they contain free Gasoline dispenser fuel filters intended for disposal must be managed as a hazardous waste,

dm.mo.gov/pubs/pub117.pdf. flashpoint test or if they are not tested, the gasoline dispenser fuel filters must be managed as the wastes are at or above 0.5 mg/l (milligrams per liter) for benzene, if the filters fail the Does Your Business Generate Hazardous Waste? available on the department's Web site at hazardous waste. For more information about managing hazardous waste, see the fact sheet benzene using the Toxicity Characteristic Leaching Procedure, or TCLP If TCLP results show hazardous, the filters should be sampled for ignitability, also known as the flashpoint test, and If you choose to characterize the gasoline dispenser fuel filters to determine if the waste is

Permitted Sanitary Landfill Option

for benzene and they do not fail the flashpoint test; they are not hazardous and may be sent to a If the results of representative samples show the gasoline dispenser fuel filters are below .5 mg/l permitted sanitary landfill. Testing results must be retained for a period of three years.

Safe Gasoline Dispenser Fuel Filter Draining Practices

gasoline tank filters. gasoline spills may be dried over an open container similar to the method used to drain and dry legitimate metal recycler. Absorbent materials such as pads, socks or booms used to absorb the environment. Dry filters must then be placed in a closed container prior to being sent to a over a suitable container such as a drum or bucket so there is no release of gasoline product to If managing on-site for recycling, metal gasoline tank dispenser filters must be drained and dried

Other important draining practices are:

- Do not throw gasoline dispenser fuel filters or absorbents in the trash. Wastes containing Never place or drain gasoline dispenser fuel filters in a containment sump. This violates Department of Agriculture regulations.
- Do not dry gasoline dispenser fuel filters outdoors. Precipitation can cause the container to gasoline can cause fires or explosions. overflow and release gasoline waste to the environment.
- Do not drain gasoline dispenser fuel filters or absorbents to the sewer. Wastes containing plants and septic systems are not designed to handle these wastes. Storm sewers often gasoline can cause fires or explosions in the sewer and conventional wastewater treatment
- Do not pour gasoline on the ground. Waste gasoline from the drying of gasoline dispenser fuel drain to streams and lakes, and wastes containing gasoline can cause harm to fish and other
- filters or absorbents can contaminate the land, water and drinking water wells

Managing captured gasoline - Residual gasoline product must be managed according to guidance explained in the fact sheet Management of Petroleum Storage Tank Wastes available Agriculture fuel specifications. 573-751-3176. Captured gasoline product may also be sold if it meets Missouri Department of online at dnr.mo.gov/pubs/pub2040.pdf or by contacting the Hazardous Waste Program at

What contractors should know

contractors may store and accumulate the drained metal filters at their facility as long as the Contractors may transport drained metal filters to a legitimate metal recycler. Additionally, filters will be recycled as scrap metal.

state to transport or accept hazardous waste. destined for disposal, unless the contractor's site has a license, permit or certification from the fuel filters, used absorbents contaminated with gasoline or petroleum contaminated water However, contractors may not transport, store or accumulate hazardous gasoline dispenser

absorbents and petroleum contaminated water and to ensure their wastes are managed appropriately. Ultimately, the burden rests on the generator to make a hazardous determination on filters

For more information

Missouri Department of Natural Resources Hazardous Waste Program P.O. Box 176

Fax 573-526-5268 800-361-4827 or 573-751-3176 Jefferson City, MO 65102-0176

dnr.mo.gov/env/hwp/index.html

Missouri Department of Natural Resources

Hazardous Waste Program

P.O. Box 176 Tanks Compliance and Enforcement Unit

Jefferson City, MO 65102-0176

575-522-5665

tanks-compliance@dnr.mo.gov

Missouri Department of Natural Resources

Solid Waste Management Program

P.O. Box 176

Jefferson City, MO 65109-0176 800-361-4827 or 573-751-5401

dnr.mo.gov/env/swmp/index.html

Fax 573-526-3902

Missouri Department of Agriculture

P.O. Box 630 Petroleum/Propane/Anhydrous Ammonia Program

573-751-5636 Jefferson City, MO 65101-0630

mda.mo.gov/wm/ppaa.htm

Ć

ATTACHMENT 12 Page 3 of 3

	ı	. /	*
	ı	M	2
	I		Ä
l	ı		Ų
	I		
	ı	and the same of	h
١	1		
	ı		3
l	I		. /
١	ı	,N	
١	ł	7>	
l	I	RAPID	
I	I	j	
ļ	I		
I	I	-	
Ì	I	77	
	ı	~	
	Ì	П	
1	ı	0	
	ı	0	
	1		
	ı	-	
l	1		
ļ		RECOVER	

~

877.3.RAPREC® 877.372.7732 - TOLL FREE 877.572.7732 - FAX www.raprec.com

05-10-'12 11:34 FROM-U- PICK IT 816-457-6064 T-422 P0056/0088 F-795 2 2 2 2 2 2 () #: ddress: ontractor: ((Pick - JT OMMENTS MAKE/CYL I hereby accept performance and charges as being satisfactory and acknowledge that the equipment has been left in good condition.

Environmentally harmful refrigerants have been removed in compliance with section 60% of the Clean Air Act.

Work has been completed by an independently owned and operated translated business. E ジャウ りより 1808C OF 6 本年 TION E. WINNER 李 WOLVE / TEACHOR 42 173 800 787 P C S <u>ک</u> (N) 28 8 7 Phone #: 8/6-24-15.48 71223567 DONAGS OF ROAD 0843190 R109406 5864840 8109368 DE YES SERIES Job-Site Information 20% TVINES Form Tomb Continued Da Site Name: KC くく 825 STAL S NEO N. S. W. X13/1/2 X 13 1/A J.K.IX XBYA #H-14X 6 Dillie LABOR MIX **R-22** Y 334 Date: IC . IZ - II WO#: 45536 REF 808 mi TAN. W 4 LABOR Alle her Dosse K Draw GRAND TOTAL: 18 284.00 0.00 ID#/INEO ROCATION) 3.00 PRICE 124.00 -\$ 710.00 PRACE 000 30.00 33500 80.8 800 100 ex TOLY 0.00 100,00 (5 ce 00

REFRIGERANT ABATEMENT EXPERTS®

Technician's Signature

Ñ

Customer's Signature

SIDELIX SOMMING

디디 중 중

SBP# 131658

1000-7CF-0TQ

to transit plant

11426727

MATAGOR

WITH CONTRACT OF THE CONTRACT

800018 8900019

XMITTEOR COCCULINK

800008

WHO TO HOO

9900011 8800010

MINS 2000 DOOKS UNK

SERVICE)

DOGGUEN.

8900012 8900012

8900014

ATTACHMENT 4 Page 1 of 2

TECH LOGIE

05-10-'12 11:35 FROM-U- PICK IT

816-457-6064 3-10K-IT-1 CUPS 7700 E.2: " N 3AS CITY, 61125 T-422 P0058/0088 F-795
: 1:36 No.: 1 2:787
TO: ...MOUNT: 1,113.0

Discour, Paym 4 u ment Invoice Inv Remark r: ber 1157112 Taken Amo Nun Date 1,100.05 1:1652 0285 12/01/12 ERS I CIL. .0018

Exide Battery Payment

ATTACHMENT 14 Page 2 of 2

The above mination re is to the pe set made by cele Technical partition in a submitter of position of the period o

E: ide no k in provides our remitte is by mail for as ments. As a ments is a provided of the p

Thank you is rance to us coopers if

PHOTO LOG

Facility Name / City: U-Pick-lt.

Kansas City, MO

Facility ID #: Non-notifier Date: February 9-10, 2012

Photographer: Dedriel Newsome

Type of Camera: Olympus Stylus 720 SW, Serial #: A93671407

Digital Recording Media: Flashcard

All digital photos were copied by: Dedriel Newsome on 2/15/2012

All digital photos were copied to: CD-R

Original copy is stored in: CD-R. Digital photos were downloaded to CD-R all by Dedriel Newsome.

No changes were made in the original image files prior to storage on the CD-R.

Report		i musicus i ni karasigani ka kasaning musicus ganda magicus galan		File Name	Description
Photo #	Photographer	Date	Approx. Time	(P2xxxxxx.jpg)	,
1	Dedriel Newsome	02/09/12	11:05 AM	090001	2/9/2012 (facing N) - Yard Office - One unlabeled approximately 3/4th full 10-gallon tub of mercury
,					switches containing the mercury ampules.
2	Dedriel Newsome	02/09/12	11:05 AM	090002	(facing N) - Yard Office - Close-up of one of the mercury ampules in a mercury switch located in the 10-
					gallon tub of mercury switches containing the mercury ampules shown in photo 1.
3	Dedriel Newsome	02/09/12	11:06 AM	090003	(facing SE) - Yard Office - Approximately 1-gallon tub of mercury ampules that had been removed from the
			ì		mercury switches. Inside the tub is shown in photo 4.
4	Dedriel Newsome	02/09/12	11:06 AM	090004	Yard Office - Approximately 1-gallon tub of mercury ampules that had been removed from the mercury
	ń				switches. The tub is shown in photos 3 and 5.
5	Dedriel Newsome	02/09/12	11:07 AM	090005	Yard Office - Approximately 1-gallon tub of mercury ampules that had been removed from the mercury
					switches. Inside the tub is shown in photo 4.
6	Dedriel Newsome	02/09/12	11:09 AM	090006	(facing SE) - Telephone System Room - One open unlabeled box of 11 spent lamps being stored. Inside
	'				the box is shown in photo 7.
7	Dedriel Newsome	02/09/12	11:10 AM	090007	Telephone System Room - Inside the box of 11 spent lamps being stored. The box is shown in photo 6.
8	Dedriel Newsome	02/09/12	11:26 AM	090008	(facing N) – Storage Tank Room – Spent gasoline line filters being stored inside the gasoline tank
Ç.	Dediler Newsound	GEIGGIAE	11.207	03000	containment unit that had about and inch of waste gasoline.
9	Dedriel Newsome	02/09/12	11:27 AM	090009	(facing NE) - Storage Tank Room - Storage tanks with containment (from left to right) used oil, used anti-
	memoritor rawarantin	Academic and Mark a ware		and here and alter des line.	freeze, and waste gasoline. Spills on floor dry observed on floor.
10	Dedriel Newsome	02/09/12	11:27 AM	090010	(facing NE) - Storage Tank Room - Spent gasoline line filters being stored outside the gasoline tank
	,	A Part of the Part		.,	containment unit.
11	Dedriel Newsome	02/09/12	11:28 AM	090011	(facing NE) - Storage Tank Room - Storage tanks with containment (from left to right) used oil, used anti-
					freeze, and waste gasoline. Spills on floor dry observed on floor.
12	Dedriel Newsome	02/09/12	11:40 AM	090012	(facing NE) - Pop Hood Area - Two black approximately full unknown 5-gallon pails that were removed
					from scrap cars the beginning of last week (around 1/30/2012). One in poor condition and labeled used
					anti-freeze and the other had a product label for some type of finish.
13	Dedriel Newsome	02/09/12	11:45 AM	090013	(facing SE) – Area that is NE of the Pop Hood Area – Five 55-gallon drums of waste removed from the
			1		Rack Area used oil sump about 6 to 8 months ago. Mr. Moran estimated that the total volume between all
					five (3 approx. full and 2 partially filled) would equal about four full drums. They were all open with no
					labels. Close-ups of inside the drums are shown in photos 14, 15 and 17.

05-10-'12 11:35 FROM-U- P	PICK IT	816-457-6064	T-422	P0060/0088 F-795

Report	I			File Name	Description
Photo #	Photographer	Date	Approx. Time	(P2xxxxxx.jpg)	
14	Dedriel Newsome	02/09/12	11:45 AM	090014	(facing SE) – Area that is NE of the Pop Hood Area – Close-up of the drums shown in photo 13. Drums of waste removed from the Rack Area used oil sump about 6 to 8 months ago. They were all open with no labels.
15	Dedriel Newsome	02/09/12	11:45 AM	090015	Area that is NE of the Pop Hood Area — Close-up of the drums shown in photo 13. Drums of waste removed from the Rack Area used oil sump about 6 to 8 months ago. They were all open with no labels.
16	Dedriel Newsome	02/09/12	· 11:46 AM	090016	(facing SE) — Area that is NE of the Pop Hood Area — Five 55-gallon drums of waste removed from the Rack Area used oil sump about 6 to 8 months ago. Mr. Moran estimated that the total volume between all five (3 approx. full and 2 partially filled) would equal about four full drums. They were all open with no labels. Close-ups of inside the drums are shown in photos 14, 15 and 17. Spills also observed around the drums.
17	Dedriel Newsome	02/09/12	11:47 AM	090017	Area that is NE of the Pop Hood Area – Close-up of the drums shown in photo 13. Drums of waste removed from the Rack Area used oil sump about 6 to 8 months ago. They were all open with no labels.
18	Dedriei Newsome	02/09/12	11:50 AM	090018	(facing N) — Area on West Side of Site (see attachment 8C for photo location) — Apparent oil stains observed on the ground.
19	Dedriel Newsome	02/09/12	11:50 AM	090019	(facing W) – Area on West Side of Site (see attachment 8C for photo location) – Apparent oil spills and stains observed on the ground.
20	Dedriel Newsome	02/09/12	11:50 AM	090020	(facing NW) — Area on West Side of Site (see attachment 8C for photo location) — Apparent oil spills and stains observed on the ground and stain leading to drain. Close-ups shown in photos 21 through 24.
21	Dedriel Newsome	02/09/12	11:51 AM	090021	(facing NW) – Area on West Side of Site (see attachment 8C for photo location) – Apparent oil spills observed on the ground and stain leading to drain. See photo 20.
22	Dedriel Newsome	02/09/12	11:51 AM	090022	(facing NW) – Area on West Side of Site (see attachment 8C for photo location) – Apparent oil spills observed on the ground and stain leading to drain. Close-up of photo 21.
23	Dedriel Newsome	02/09/12	11:51 AM	090023	(facing NW) – Area on West Side of Site (see attachment 8C for photo location) – Apparent oil spills and stains observed on the ground and stain leading to drain. Close-up of oil spill to drain shown in photo 20.
24	Dedriel Newsome	02/09/12	11:52 AM	090024	(facing NE) – Area on West Side of Site (see attachment 8C for photo location) – Apparent oil spills and stains observed on the ground and stain leading to drain. Close-up of oil spill to drain shown in photo 20.
25	Dedriel Newsome	02/09/12	11:55 AM	. 090025	(facing NE) – Area on West Side of Site (see attachment 8C for photo location) – Apparent oil spills and stains observed on a concrete pad with no containment and water puddle with oil sheen next to pad. Close-ups shown in photos 26 and 27.
26	Dedriel Newsome	02/09/12	11:55 AM	090026	(facing NE) – Area on West Side of Site (see attachment 8C for photo location) – Close-up of oil sheen in water puddle on ground shown in photo 25.
27	Dedriel Newsome	02/09/12	11:56 AM	090027	(facing E) – Area on West Side of Site (see attachment 8C for photo location) – Close-up of oil spills and stains and water puddle in photo 25.
28	Dedriel Newsome		11:56 AM	, 090028	(facing NE) – Area on West Side of Site (see attachment 8C for photo location) – Apparent oil spills and stains observed on a concrete pad with no containment.
29	Dedriel Newsome		11:59 AM	090029	(facing NW) – Area on West Side of Site (see attachment 8C for photo location) – Apparent oil stains observed tracked on dirt drive way between the rows of scrap cars.
30	Dedriel Newsome	02/09/12	12:04 PM	090030	(facing E) – Area on North Side of Site (see attachment 8C for photo location) – Apparent oil stains observed on concrete pad that Mr. Moran believed was covered in millings to fill in holes in the concrete pad over the years.
31	Dedriel Newsome	02/09/12	12:05 PM	090031	(facing SE) – Area on North Side of Site (see attachment 8C for photo location) – Apparent oil spills and stains observed on concrete pad that Mr. Moran believed was covered in millings to fill in holes in the concrete pad over the years.

Report				File Name	Description .
Photo #	Photographer	Date	Approx. Time	(P2xxxxxx.jpg)	
32	Dedriel Newsome	02/09/12	12:06 PM	090032	(facing W) - Area on North Side of Site (see attachment 8C for photo location) - Apparent oil stains
					observed on concrete pad that Mr. Moran believed was covered in millings to fill in holes in the concrete
					lpad over the years.
33	Dedriel Newsome	02/09/12	12:06 PM	090033	(facing E) - Area on North Side of Site (see attachment 8C for photo location) - Apparent oil stains
					observed on concrete pad that Mr. Moran believed was covered in millings to fill in holes in the concrete
041041041041041041		***************************************			pad over the years.
34	Dedriel Newsome	02/09/12	12:15 PM	090034	(facing N) - Area on East Side of Site (see attachment 8C for photo location) - Apparent oil stains
				alianetajojo jakin k	observed on a concrete pad with no containment and ground
35	Dedriel Newsome	02/09/12	12:15 PM	090035	(facing NE) - Area on East Side of Site (see attachment 8C for photo location) - Apparent oil stains
				***************************************	observed on a concrete pad with no containment and ground.
36	Dedriel Newsome	02/09/12	12:16 PM	090036	(facing S) - Area on East Side of Site (see attachment 8C for photo location) - Apparent oil stains observed
					on a concrete pad with no containment and ground.
37	Dedriel Newsome	02/09/12	12:16 PM	090037	(facing NE) - Area on East Side of Site (see attachment 8C for photo location) - Apparent oil stains
					observed on a concrete pad with no containment and ground.
38	Dedriel Newsome	02/09/12	12:22 PM	090038	(facing E) - Crusher Area where engines and transmissions are pulled - Scrap parts bin with thick layer of
yanganganganganganganganganganganganganga					joily floor dry.
39	Dedriel Newsome	02/09/12	12:22 PM	090039	(facing E) - Crusher Area where engines and transmissions are pulled - Scrap parts bin with thick layer of
	, , , , , , , , , , , , , , , , , , , ,				oily floor dry.
. 40	Dedriel Newsome	02/10/12	10:07 AM	100040	(facing SW) - Rack Area where vehicle fluids (gasoline, diesel, oil, antifreeze, transmission fluid) are
***************************************		August 12 August 14		coccernment coccer	drained. Thick layer of contaminated floor dry on floor.
41	Dedriel Newsome	02/10/12	10:08 AM	100041	(facing SE) - Electrical Room - Old PCB containing transformer to be removed.
42	Dedriel Newsome	02/10/12	10:08 AM	100042	(facing S) - Electrical Room - Old PCB containing transformer unit to be removed and area where old unit
40		00140140	20.00.335	200020	that was removed was located.
43	Dedriel Newsome	02/10/12	10:09 AM	100043	(facing SE) - Electrical Room - Area where old PCB containing transformer was removed located next to
44	Dedriel Newsome	02/10/12	10:10 AM	100044	the transformer unit to be removed.
****	Dégliei Newsonie	02/10/12	IO, IO AM	100044	(facing SE) - Electrical Room - Old PCB containing transformer unit to be removed with close-up of catch
45	Dedriel Newsome	02/10/12	10:12 AM	100045	(facing SW) – Core Return Area – Tote where used oil is accumulated including the used oil generated
40	Dediter Memoritie	VE2 101 14.	10.12.744	100040	from household do-it-yourselfers.
46	Dedriel Newsome	02/10/12	10:14 AM	100046	(facing SW) – Rack Area where vehicle fluids (gasoline, diesel, oil, antifreeze, transmission fluid) are
#./P.	Properties (Acta Continue	Straint 1 Str 1 Au	100.13.030	I WOOTO	drained. Thick layer of contaminated floor dry on floor.
47	Dedriel Newsome	02/10/12	10:14 AM	100047	(facing NW) - Pop Hood Area - Area where vehicle fluids are pumped out including power steering, brake
***		4300 - 41 - 440	1.4	The second of the	fluid, and windshield wiper fluid. Also, tire lug nuts are loosened and trash, batteries and mercury switches
					are removed. Two piles of trash to be added into a crushed car for disposal.
48	Dedriel Newsome	02/10/12	10:16 AM	100048	(facing NE) - Area on South Side of Site at Customer Entrance (see attachment 8C for photo location) -
					Apparent oil stains observed on the concrete ground under yellow engine heist leading to drain located
					behind concrete barriers. Close-ups shown in photos 49 and 50.
49	Dedriel Newsome	02/10/12	10:16 AM	100049	(facing W) - Area on South Side of Site at Customer Entrance (see attachment 8C for photo location) -
					Apparent oil stains observed on the concrete ground leading from engine heist area shown in photo 48 to
		,	`		drain located behind concrete barriers.
50	Dedriel Newsome	02/10/12	10:16 AM	100050	(facing SW) - Area on South Side of Site at Customer Entrance (see attachment 8C for photo location) -
					Apparent oil stains observed on the concrete ground under yellow engine heist leading to drain located
	1			h	behind concrete barriers shown in photos 48 and 49.
51	Dedriel Newsome	02/10/12	10:19 AM	100051	(facing NE) - Yard Office - 1-gallon tub of mercury ampules on file cabinet and desk where ampules are
					removed from switches without containment.

U-Pick-It Photographs Kansas City, MO 2/9-10/2012 Photos taken by Dedriel Newsome



PHOTO 1, 2/9/2012 (facing N) — Yard Office — One unlabeled approximately 3/4th full 10-gallon tub of mercury switches containing the mercury ampules. D. Newsome




PHOTO 2, 2/9/2012 (facing N) — Yard Office — Close-up of one of the mercury ampules in a mercury switch located in the 10-gallon tub of mercury switches containing the mercury ampules shown in photo 1.

D. Newsome




PHOTO 3, 2/9/2012 (facing SE) – Yard Office – Approximately
1-gallon tub of mercury ampules that had been removed from the
mercury switches. Inside the tub is shown in photo 4. D. Newsome



PHOTO 4, 2/9/2012 – Yard Office – Approximately 1-gallon tub of mercury ampules that had been removed from the mercury switches. The tub is shown in photos 3 and 5. D. Newsome




PHOTO 5, 2/9/2012 – Yard Office – Approximately 1-gallon tub of mercury ampules that had been removed from the mercury switches. Inside the tub is shown in photo 4. D. Newsome




PHOTO 6, 2/9/2012 (facing SE) – Telephone System Room – One open unlabeled box of 11 spent lamps being stored. Inside the box is shown in photo 7. D. Newsome

816-457-6064



PHOTO 7, 2/9/2012 – Telephone System Room – Inside the box of 11 spent lamps being stored. The box is shown in photo 6. D. Newsome



PHOTO 8, 2/9/2012 (facing N) — Storage Tank Room — Spent gasoline line filters being stored inside the gasoline tank containment unit D. Newsome that had about and inch of waste gasoline.




PHOTO 9, 2/9/2012 (facing NE) - Storage Tank Room - Storage tanks with containment (from left to right) used oil, used anti-freeze, and with containment (from left to right) used on, used and waste gasoline. Spills on floor dry observed on floor. D. Newsome



PHOTO 10, 2/9/2012 (facing NE) - Storage Tank Room - Spent gasoline line filters being stored outside the gasoline tank containment unit. D. Newsome

816-457-6064




PHOTO 11, 2/9/2012 (facing NE) — Storage Tank Room — Storage tanks with containment (from left to right) used oil, used anti-freeze, and waste gasoline. Spills on floor dry observed on floor.

D. Newsom




PHOTO 12, 2/9/2012 (facing NE) – Pop Hood Area – Two black approximately full unknown 5-gallon pails that were removed from scrap cars the beginning of last week (around 1/30/2012). One in poor condition and labeled used anti-freeze and the other had a product label for some type of finish. D. Newsome

816-457-6064




PHOTO 13, 2/9/2012 (facing SE) — Area that is NE of the Pop Hood Area — Five 55-gallon drums of waste removed from the Rack Area used oil sump about 6 to 8 months ago. Mr. Moran estimated that the total volume between all five (3 approx. full and 2 partially filled) would equal about four full drums. They were all open with no labels. Close-ups of inside the drums are shown in photos 14, 15 and 17. D. Newsome



PHOTO 14, 2/9/2012 (facing SE) — Area that is NE of the Pop Hood Area — Close-up of the drums shown in photo 13. Drums of waste removed from the Rack Area used oil sump about 6 to 8 months ago. They were all open with no labels.

D. Newsome



PHOTO 15, 2/9/2012 – Area that is NE of the Pop Hood Area – Close-up of the drums shown in photo 13. Drums of waste removed from the Rack Area used oil sump about 6 to 8 months ago. They were all open with no labels. D. Newsome



PHOTO 16, 2/9/2012 (facing SE) – Area that is NE of the Pop Hood Area – Five 55-gallon drums of waste removed from the Rack Area used oil sump about 6 to 8 months ago. Mr. Moran estimated that the total volume between all five (3 approx. full and 2 partially filled) would equal about four full drums. They were all open with no labels. Close-ups of inside the drums are shown in photos 14, 15 and 17. Spills also observed around the drums. D. Newsome



PHOTO 17, 2/9/2012 – Area that is NE of the Pop Hood Area – Closeup of the drums shown in photo 13. Drums of waste removed from the Rack Area used oil sump about 6 to 8 months ago. They were all open with no labels. D. Newsome




PHOTO 18, 2/9/2012 (facing N) – Area on West Side of Site (see attachment 8C for photo location) – Apparent oil stains observed on the ground.

D. Newsome




PHOTO 19, 2/9/2012 (facing W) — Area on West Side of Site (see attachment 8C for photo location) — Apparent oil spills and stains observed on the ground.

D. Newsome




PHOTO 20, 2/9/2012 (facing NW) — Area on West Side of Site (see attachment 8C for photo location) — Apparent oil spills and stains observed on the ground and stain leading to drain. Close-ups shown in photos 21 through 24. D. Newsome



PHOTO 21, 2/9/2012 (facing NW) — Area on West Side of Site (see attachment 8C for photo location) — Apparent oil spills observed on the ground and stain leading to drain. See photo 20. D. Newsome



PHOTO 22, 2/9/2012 (facing NW) — Area on West Side of Site (see attachment 8C for photo location) — Apparent oil spills observed on the ground and stain leading to drain. Close-up of photo 21.

D. Newsome



PHOTO 23, 2/9/2012 (facing NW) — Area on West Side of Site (see attachment 8C for photo location) — Apparent oil spills and stains observed on the ground and stain leading to drain. Close-up of oil spill to drain shown in photo 20. D. Newsome




PHOTO 24, 2/9/2012 (facing NE) — Area on West Side of Site (see attachment 8C for photo location) — Apparent oil spills and stains observed on the ground and stain leading to drain. Close-up of oil spill to drain shown in photo 20. D. Newsome



PHOTO 25, 2/9/2012 (facing NE) — Area on West Side of Site (see attachment 8C for photo location) — Apparent oil spills and stains observed on a concrete pad with no containment and water puddle with oil sheen next to pad. Close-ups shown in photos 26 and 27. D. Newsome




PHOTO 26, 2/9/2012 (facing NE) — Area on West Side of Site (see attachment 8C for photo location) — Close-up of oil sheen in water puddle on ground shown in photo 25. D. Newsome




PHOTO 27, 2/9/2012 (facing E) — Area on West Side of Site (see attachment 8C for photo location) — Close-up of oil spills and stains and water puddle in photo 25. D. Newsome



PHOTO 28, 2/9/2012 (facing NE) — Area on West Side of Site (see attachment 8C for photo location) — Apparent oil spills and stains observed on a concrete pad with no containment. D. Newsome



PHOTO 29, 2/9/2012 (facing NW) — Area on West Side of Site (see attachment 8C for photo location) — Apparent oil stains observed tracked on dirt drive way between the rows of scrap cars.

D. Newsome



PHOTO 30, 2/9/2012 (facing E) — Area on North Side of Site (see attachment 8C for photo location) — Apparent oil stains observed on concrete pad that Mr. Moran believed was covered in millings to fill in holes in the concrete pad over the years.

D. Newsome



PHOTO 31, 2/9/2012 (facing SE) – Area on North Side of Site (see attachment 8C for photo location) – Apparent oil spills and stains observed on concrete pad that Mr. Moran believed was covered in millings to fill in holes in the concrete pad over the years.

D. Newsome



PHOTO 32, 2/9/2012 (facing W) — Area on North Side of Site (see attachment 8C for photo location) — Apparent oil stains observed on concrete pad that Mr. Moran believed was covered in millings to fill in holes in the concrete pad over the years.

D. Newsome



PHOTO 33, 2/9/2012 (facing E) - Area on North Side of Site (see attachment 8C for photo location) - Apparent oil stains observed on concrete pad that Mr. Moran believed was covered in millings to fill D. Newsome in holes in the concrete pad over the years.



PHOTO 34, 2/9/2012 (facing N) – Area on East Side of Site (see attachment 8C for photo location) - Apparent oil stains observed on a concrete pad with no containment and ground. D. Newsome



PHOTO 35, 2/9/2012 (facing NE) – Area on East Side of Site (see attachment 8C for photo location) – Apparent oil stains observed on a concrete pad with no containment and ground. D. Newsome




PHOTO 36, 2/9/2012 (facing S) – Area on East Side of Site (see attachment 8C for photo location) - Apparent oil stains observed on a concrete pad with no containment and ground. D. Newsome



PHOTO 37, 2/9/2012 (facing NE) — Area on East Side of Site (see attachment 8C for photo location) — Apparent oil stains observed on a concrete pad with no containment and ground. D. Newsome




PHOTO 38, 2/9/2012 (facing E) – Crusher Area where engines and transmissions are pulled – Scrap parts bin with thick layer of oily floor dry.

D. Newsome




PHOTO 39, 2/9/2012 (facing E) – Crusher Area where engines and transmissions are pulled – Scrap parts bin with thick layer of oily floor dry.

D. Newsome




PHOTO 40, 2/10/2012 (facing SW) — Rack Area where vehicle fluids (gasoline, diesel, oil, antifreeze, transmission fluid) are drained.

Thick layer of contaminated floor dry on floor.

D. Newsome




PHOTO 41, 2/10/2012 (facing SE) – Electrical Room – Old PCB containing transformer to be removed. D. Newsome




PHOTO 42, 2/10/2012 (facing S) — Electrical Room — Old PCB containing transformer unit to be removed and area where old unit that was removed was located. D. Newsome



PHOTO 43, 2/10/2012 (facing SE) – Electrical Room – Area where old PCB containing transformer was removed located next to the transformer unit to be removed. D. Newsome




PHOTO 44, 2/10/2012 (facing SE) - Electrical Room - Old PCB containing transformer unit to be removed with close-up of catch pan. D. Newsome



PHOTO 45, 2/10/2012 (facing SW) — Core Return Area — Tote where used oil is accumulated including the used oil generated from household do-it-yourselfers. D. Newsome




PHOTO 46, 2/10/2012 (facing SW) – Rack Area where vehicle fluids (gasoline, diesel, oil, antifreeze, transmission fluid) are drained.

Thick layer of contaminated floor dry on floor.

D. Newsome




PHOTO 47, 2/10/2012 (facing NW) - Pop Hood Area - Area where vehicle fluids are pumped out including power steering, brake fluid, and windshield wiper fluid. Also, tire lug nuts are loosened and trash, batteries and mercury switches are removed. Two piles of trash to be added into a crushed car for disposal. D. Newsome



PHOTO 48, 2/10/2012 (facing NE) — Area on South Side of Site at Customer Entrance (see attachment 8C for photo location) -Apparent oil stains observed on the concrete ground under yellow engine heist leading to drain located behind concrete barriers. engine heist leading to drain located occurs.

Close-ups shown in photos 49 and 50. D. Newsome

816-457-6064



PHOTO 49, 2/10/2012 (facing W) — Area on South Side of Site at Customer Entrance (see attachment 8C for photo location) — Apparent oil stains observed on the concrete ground leading from engine heist area shown in photo 48 to drain located behind concrete barriers.

D. Newsome




PHOTO 50, 2/10/2012 (facing SW) – Area on South Side of Site at Customer Entrance (see attachment 8C for photo location) – Apparent oil stains observed on the concrete ground under yellow engine heist leading to drain located behind concrete barriers shown in photos 48 and 49. D. Newsome




PHOTO 51, 2/10/2012 (facing NE) — Yard Office — 1-gallon tub of mercury ampules on file cabinet and desk where ampules are removed from switches without containment.

D. Newsomewa